4	1		of 2 ?	>	ÞΙ	\bigcirc	Θ	100%	~		ф	Find Next	
---	---	--	--------	---	----	------------	----------	------	---	--	---	-------------	--



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En	Automob	ile					
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPC22001235/Eqf3					
	300 BEACH ROAD			Date:	09/02/2022					
	#17-04/07 THE CC	NCOURSESINGAPORE 199555			1.000					
				Code:						
. Policy Particulars :- (THIRD PARTY CLAIM)										
	Insured Veh.	GBD 9704Z	Veh. Inspected	l	GBF 6427H					
	Policy No.		Coverage (\$)		0.00					
	Claim No.	21/22/22/VC00/025441	Excess (\$)		0.00					
	Assign From	GERALD POH	Assign Date		09/02/2022					
<u>.</u>		Vehicle Partic	ulars & Conditi	on						
	Make & Model		c.c 0							
	Engine No.	HIDDEN	Year of Reg.							
	Chassis No.		Colour							
	Odometer	-	Steering							
	Brakes		Modification							
	General									
3.		Condition	ons of Tyres							
		Size	Make		Balance					
	R/H Front Tyre				mm					
	L/H Front Tyre				mm					
	R/H Rear Tyre				mm					
	L/H Rear Tyre				mm					
	•	Description	on of Damages		•					
i.	General Information									
	Accident Date	08/02/2022	Inspection Dat	e	10/02/2022					
	Survey held at	V-TECH AUTO SERVICE								
	No.1 SOON LEE STREET									
		#06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605								
ia.		Re	emarks							
	B) THE REPAIR E	ON WAS CONDUCTED ON A "WI' STIMATE WAS NOT PRESENTED /AS TOLD TO PREPARE THE EST EASE FIND DAMAGED VEHICLE	AT THE TIME OF TIMATE.	INSPEC						