

ASS. REC. BY:

REF:

CTZ / 22001239/kg

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-6 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SND 7566B

Yr Regn:

01, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Noah

c.c

1797

Colour

M.P. white

A/C:

Insured / Std / NI / NA

Sp. Reading

4112

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZWR 80. 0503103

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

6/2/22

D.O.I.

9/2/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

S - RS. \$

Fees

Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Date: 08/02/2022

Vehicle No: SND7566B

Model: TOYOTA NOAH HYBRID 1.8X

Chassis: ZWR800503103

Reg. Year: 2021

Third Party Insurer: CHINA TAIPING

Third Party Veh No: GBB2733X

Date of Accident: 06/02/2022

Estimator: KIT

Surveyor:

*Not with hold*

*Running B & pain*

*4-8 days*

## ESTIMATE

| NO. | DESCRIPTION                           | QTY | UNIT S\$ | AMOUNT S\$                |   |
|-----|---------------------------------------|-----|----------|---------------------------|---|
| 1   | REAR TAILGATE                         | 1   |          | <i>Ph</i> \$1,988.80      | ✓ |
| 2   | REAR TAILGATE WINDSCREEN GLASS        | 1   |          | <i>Shatter</i> \$1,290.10 | ✓ |
| 3   | REAR TAILGATE WINDSCREEN MOULDING     | 1   |          | <i>Ph</i> \$116.30        | ✓ |
| 4   | REAR TAILGATE WIPER ARM               | 1   |          | <i>Ph</i> \$149.80        | X |
| 5   | REAR TAILGATE WIPER MOTOR             | 1   |          | <i>Ph</i> \$873.20        | X |
| 6   | REAR TAILGATE "LOGO" EMBLEM           | 1   |          | <i>Ph</i> \$87.60         | ✓ |
| 7   | REAR TAILGATE OUTER CHROME GARNISH    | 1   |          | <i>CR</i> \$832.10        | ✓ |
| 8   | REAR TAILGATE "HYBRID" EMBLEM         | 1   |          | <i>Ph</i> \$85.80         | ✓ |
| 9   | REAR TAILGATE MECHANISM LOCK          | 1   |          | \$495.20                  | ✓ |
| 10  | REAR TAILGATE INNER HANDLE COVER      | 1   |          | <i>Ph</i> \$52.40         | X |
| 11  | REAR TAILGATE INNER TRIM BOARD        | 1   |          | <i>Ph</i> \$570.10        | X |
| 12  | REAR TAILGATE INNER TRIM BOARD TOP    | 1   |          | <i>Ph</i> \$427.10        | X |
| 13  | REAR TAILGATE INNER TRIM BOARD LH     | 1   |          | <i>Ph</i> \$342.00        | X |
| 14  | REAR TAILGATE INNER TRIM BOARD RH     | 1   |          | <i>Ph</i> \$342.00        | X |
| 15  | REAR TAILGATE WEATHERSTRIP            | 1   |          | \$380.70                  | ✓ |
| 16  | REAR TAILLAMP LH                      | 1   |          | <i>CM</i> \$820.80        | ✓ |
| 17  | REAR TAILLAMP RH                      | 1   |          | <i>Ph</i> \$820.80        | X |
| 18  | REAR TAILLAMP LOWER GARNISH LH        | 1   |          | \$176.20                  | ✓ |
| 19  | REAR TAILLAMP LOWER GARNISH RH        | 1   |          | <i>Ph</i> \$176.20        | X |
| 20  | REAR TAILLAMP LOWER BRACKET LH        | 1   |          | <i>Ph</i> \$115.20        | X |
| 21  | REAR TAILLAMP LOWER BRACKET RH        | 1   |          | <i>Ph</i> \$115.20        | X |
| 22  | REAR SIDE GARNISH LH                  | 1   |          | <i>Ph</i> \$197.80        | X |
| 23  | REAR SIDE GARNISH RH                  | 1   |          | <i>Ph</i> \$197.80        | X |
| 24  | REAR BUMPER                           | 1   |          | <i>Ph</i> \$823.20        | ✓ |
| 25  | REAR BUMPER SIDE RETAINER LH          | 1   |          | <i>Ph</i> \$156.70        | X |
| 26  | REAR BUMPER SIDE RETAINER RH          | 1   |          | <i>Ph</i> \$156.70        | X |
| 27  | REAR BUMPER TOW HOOK COVER            | 1   |          | <i>Ph</i> \$55.80         | X |
| 28  | REAR BUMPER REFLECTOR LH              | 1   |          | <i>Ph</i> \$124.80        | X |
| 29  | REAR BUMPER REFLECTOR RH              | 1   |          | <i>Ph</i> \$124.80        | X |
| 30  | REAR BUMPER ANTENNA SENSOR            | 1   |          | \$150.90                  | ✓ |
| 31  | REAR END PANEL                        | 1   |          | \$914.60                  | ✓ |
| 32  | REAR END PANEL INNER TOP GARNISH      | 1   |          | <i>Ph</i> \$207.30        | ✓ |
| 33  | REAR FLOOR PANEL                      | 1   |          | <i>Ph</i> \$698.10        | X |
| 34  | REAR FLOOR PANEL INNER TOP CARPET     | 1   |          | <i>Ph</i> \$630.70        | X |
| 35  | REAR FLOOR PANEL INNER TOP CARD BOARD | 1   |          | <i>Ph</i> \$830.20        | X |
| 36  | REAR FENDER INNER TRIM BOARD LH       | 1   |          | <i>Ph</i> \$482.50        | X |

Date: 08/02/2022  
 Vehicle No: SND7566B  
 Model: TOYOTA NOAH HYBRID 1.8X  
 Chassis: ZWR800503103  
 Reg.Year: 2021

Third Party Insurer: CHINA TAIPING  
 Third Party Veh No: GBB2733X  
 Date of Accident: 06/02/2022  
 Estimator: KIT  
 Surveyor:

|    |                                 |   |  |                         |
|----|---------------------------------|---|--|-------------------------|
| 37 | REAR FENDER INNER TRIM BOARD RH | 1 |  | <i>pn</i> \$482.50      |
|    |                                 |   |  |                         |
|    |                                 |   |  | SUB TOTAL \$16,492.00   |
|    |                                 |   |  | LESS 25% \$4,123.00     |
|    |                                 |   |  | PARTS TOTAL \$12,369.00 |

| NO. | SPECIAL NETT                             | QTY | UNIT S\$ | AMOUNT S\$           |
|-----|------------------------------------------|-----|----------|----------------------|
| 1   | REAR TAILGATE WINDSCREEN SEALANT         | 1   |          | <i>nn</i> \$100.00   |
| 2   | REAR TAILGATE OUTER CHROME GARNISH CLIPS | 1   |          | <i>nn</i> \$20.00    |
| 3   | REAR TAILGATE REVERSE CAMERA             | 1   |          | <i>pn</i> \$300.00   |
| 4   | REAR NUMBER PLATE WITH HOLDER            | 1   |          | <i>pn</i> \$65.00    |
| 5   | REAR TAILGATE INNER TRIM BOARD CLIPS     | 1   |          | <i>nn</i> \$30.00    |
| 6   | REAR TAILLAMP CLIPS LH                   | 1   |          | <i>nn</i> \$20.00    |
| 7   | REAR TAILLAMP CLIPS RH                   | 1   |          | <i>nn</i> \$20.00    |
| 8   | REAR BUMPER CLIPS                        | 1   |          | <i>nn</i> \$50.00    |
| 9   | REAR BUMPER REVERSE SENSOR               | 1   |          | \$300.00             |
| 10  | REAR END PANEL JOINT SEALANT             | 1   |          | \$80.00              |
| 11  | REAR END PANEL INNER TOP GARNISH CLIPS   | 1   |          | <i>nn</i> \$20.00    |
| 12  | REAR FENDER INNER TRIM BOARD CLIPS LH    | 1   |          | <i>nn</i> \$20.00    |
| 13  | REAR FENDER INNER TRIM BOARD CLIPS RH    | 1   |          | <i>nn</i> \$20.00    |
|     |                                          |     |          |                      |
|     |                                          |     |          | S/N TOTAL \$1,045.00 |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 08/02/2022  
Vehicle No: SND7566B  
Model: TOYOTA NOAH HYBRID 1.8X  
Chassis: ZWR800503103  
Reg.Year: 2021

Third Party Insurer: CHINA TAIPING  
Third Party Veh No: GBB2733X  
Date of Accident: 06/02/2022  
Estimator: KIT  
Surveyor:

## LABOUR CHARGES:

|                                                                                                               |            |     |
|---------------------------------------------------------------------------------------------------------------|------------|-----|
| LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST ACCIDENT AREAS.                                   | \$1,400.00 | ?   |
| LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS.                                         | \$1,400.00 | 660 |
| TO TUFF KOTE & UNDERSEAL MATERIALS.                                                                           | \$100.00   | ?   |
| TO DISMANTLE & REPLACED REAR TAILGATE INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION. | \$120.00   | 60  |
| TO REMOVE & REPLACE REAR WINDSCREEN GLASS & ETC. TO EFFECT AT ACCIDENT AREA                                   | \$150.00   | 120 |
| TO DAIGNOSIS FAULT CODE & RESET MEMORY.                                                                       | \$100.00   | ?   |
| TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.                                                                    | \$80.00    | 20  |

LABOUR TOTAL \$3,350.00

KIT TOTAL \$16,764.00

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 07/02/2022 17:25 (SGT)  
Date of Accident ..... 06/02/2022 11:00 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... PIE  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SND7566B  
INSURED/POLICYHOLDER .....  
Is company? ..... Yes  
Name Of Registered Owner ..... RUEY AUTO  
Company Reg No ..... 53117371B  
Email Address ..... smartcarsboutique@gmail.com  
Mobile Phone No ..... (Phone) +65-84283690  
Alternative Phone No ..... (Office) +65-94885888

## VEHICLE PARTICULARS

Manufacturer ..... Toyota  
Model ..... NOAH HYBRID 1.8X CVT  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private hire  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private hire  
Transmission ..... Auto  
CC ..... 1800

## INSURANCE COMPANY

Name of Insurance Company ..... NTUC Income Insurance Co-operative Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... 5125545221  
Cover Note Number ..... 24/01/22 - 23/01/23

## DRIVER

Name of Driver ..... KOH KENG YAU, WILLIAM  
NRIC No ..... S1153297G

Sketch Plan



PIE  
 (A) SN075608  
 (B) 6BB2733X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT - T/20226207/2028

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time: 07/02/2022

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 07/02/2022

Reporting Centre Personnel's Signature  
 Name: (AWK)  
 HSC/PS No.:

( ) Claim Own Policy ( ) Claim Third Party ( ) Reporting Only  
 (X) Claim ODP at other workshop (OPTIMA WERE P/L)



**SINGAPORE  
POLICE FORCE**



T/20220207/2028

Police Station Of Origin:  
Serangoon North NPP  
108 Serangoon North Ave 1 #01-709  
SINGAPORE 550108  
Tel No: 1800-2849999

2 of 3

Report No. T/20220207/2028

**CONTINUATION OF REPORT**

|                                          |                        |                                                   |                                   |
|------------------------------------------|------------------------|---------------------------------------------------|-----------------------------------|
| <b>Driver</b>                            |                        |                                                   |                                   |
| <b>Name</b>                              | KOH KENG YAU, WILLIAM  | <b>ID No.</b>                                     | S1153297G                         |
| <b>Related Vehicle</b>                   | SND7566B (Car)         | <b>Contact No.</b>                                | 93375892                          |
| <b>Hospital/Clinic</b>                   | HORIZON MEDICAL CENTRE | <b>Class of Driving Licence &amp; Expiry Date</b> | Class: 3<br>Date of Expiry: NIL   |
| <b>Date Treatment</b>                    | 06/02/2022             | <b>Date Discharge</b>                             | 06/02/2022                        |
| <b>No. of Days granted Medical Leave</b> | 04                     | <b>Degree of Injury</b>                           | Slight                            |
| <b>Driver</b>                            |                        |                                                   |                                   |
| <b>Name</b>                              | Islam Mohammad Johirul | <b>ID No.</b>                                     | G8529230R                         |
| <b>Related Vehicle</b>                   | NIL                    | <b>Contact No.</b>                                | 88458185                          |
| <b>Hospital/Clinic</b>                   | NIL                    | <b>Class of Driving Licence &amp; Expiry Date</b> | Class: NIL<br>Date of Expiry: NIL |
| <b>Date Treatment</b>                    | NIL                    | <b>Date Discharge</b>                             | NIL                               |
| <b>No. of Days granted Medical Leave</b> | NIL                    | <b>Degree of Injury</b>                           | NIL                               |

**Brief Details.**

On 06/02/2022 at about 1100hrs, I was driving along PIE towards City on lane 3. I slowed down due to traffic conditions when the lorry behind me, GBB2733X was unable to slow down in time and collided with my car from the rear. I went to the doctor to as I was feeling some pain in my neck, back, and right shoulder and was given 4 days of MC. No traffic police attended and no one conveyed by ambulance. We stopped and exchanged particulars. That is all.