

# XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

Vehicle Number : SLN9215Y  
 Vehicle Model : CHEVROLET CRUZE  
 Accident Date : 06.02.2022/ 1250  
 Original Reg Date : 22.05.2017

Date : 08.02.2022  
 Chassis : KL1JA69E9GK352868  
 TP Ins. : CHINA TAIPING

*Xiao Tong.*

## ESTIMATE

1	1 pc	BONNET <i>Distorted</i>		1,650.00	✓
2	1 pc	BONNET RUBBER SEAL FRONT <i>torn</i>	93.80	281.40	✓
3	2 pc	BONNET RUBBER SEAL SIDE <i>new</i>	72.50	145.00	+
4	1 PC	BONNET INNER LOCK <i>Jammed.</i>		175.80	✓
5	1 pc	BONNET INNER INSULATOR <i>Crumpled.</i>		254.90	✓
6	2 pcs	BONNET STOPPER <i>New</i>	45.00	90.00	x
7	2 pcs	BONNET HINGES <i>new</i>	85.90	171.80	+
8	1 PC	FRONT BUMPER <i>Distorted.</i>		<del>1,485.60</del> 1,346.10	✓
9	2 pcs	FRONT BUMPER RETAINERS <i>new</i>	98.70	197.40	+
10	1 PC	FRONT BUMPER LOWER GRILLE <i>cracked.</i>		298.50	✓
11	2 pc	FRONT BUMPER LOWER SIDE GRILLE <i>new</i>	125.80	251.60	+
12	1 pc	FRONT BUMPER LOGO <i>new</i>		208.60	✓
13	1 pc	FRONT BUMPER NUMBER PLATE BASE <i>del.</i>		68.90	+
14	1 pc	FRONT BUMPER SPONGE <i>cracked</i>		198.60	✓
15	1 pc	FRONT BUMPER REINFORCEMENT <i>new</i>		1,045.80	+
16	1 pc	FRONT SUPPORT PANEL TOP GARNISH <i>del.</i>		285.90	✓
17	1 pc	FRONT BUMPER GRILLE UPPER <i>del.</i>		356.90	✓
18	1 pc	FRONT BUMPER GRILLE LOWER <i>cracked</i>		536.20	✓
19	1 pc	HEADLAMP RH <i>new</i>		2,705.60	+
20	1 pc	HEADLAMP LH <i>cracked.</i>		<del>2,705.60</del> 2,430.00	✓
21	1 pc	RADIATOR SUPOORT PANEL TOP ?		456.30	x
22	1 pc	RADIATOR		1,098.60	x
23	1 pc	RADIATOR FAN COWLING		398.60	x
24	1 pc	RADIATOR FAN BLADE AND MOTOR <i>new</i>		798.20	x
25	2 pc	RADIATOR BRACKET UPPER <i>new</i>		187.60	+
26	2 pc	RADIATOR TOP MOUNTING		135.80	+
27	2 pc	RADIATOR BRACKET LOWER		245.60	x
28	1 pc	RADIATOR TOP HOSE INLET		135.80	+
29	1 pc	RADIATOR TOP HOSE OUTLET		178.30	+
30	1 pc	TURBO INTAKE COOLER		687.50	+
31	1 pc	ATF COOLER		983.20	+
32	1 set	A/C CONDENSER		1,058.60	+
33	1 pc	INTAKE AIR DUCT AIR HOSE(AIR DUCT-RESONATOR) <i>new</i>		224.00	+
34	1 pc	INTAKE AIR RESONATOR BOX <i>new</i>		345.80	+
35	2 pc	FRONT FOGLAMP <i>new</i>		298.60	+
36	2 pc	FRONT FOGLAMP COVER <i>new</i>	154.80	309.60	+
37	1 pc	FRONT BUMPER LOWER LIP <i>new</i>		145.80	+
38	1 pc	FRONT BUMPER UNDER DUST COVER <i>new</i>		158.90	+

39	1 pc	FRONT FENDER LH <i>Not new</i>		835.60	+
40	1 pc	FRONT FENDER INNERSHIELD LH <i>Not new</i>		228.90	x.
41	1 pc	FRONT FENDER BRACKET LH <i>New</i>		145.80	x.
42	1 pc	FRONT FENDER TOP GARNISH LH <i>Not new</i>		125.60	+
43	1 pc	FRONT HORN <i>Not new</i>		201.50	+
44	1 pc	FRONT WIPER TANK WITH MOTOR <i>3M</i>		245.60	+
45	1 pc	FRONT WASHER TANK NECK <i>1m</i>		145.60	+
46	1 pc	FRONT BATTERY TRAY <i>cracked.</i>		259.50	✓

8351.20  
7516.08

23,149.00  
Less 10%  
**subtotal** 2,314.90  
**20,834.10**

**Special Nett**

1	1 set	Front number plate with casing <i>cracked.</i>		50.00	✓
2	1 set	Front fender inner shield clip <i>new</i>		30.00	+
3	1 set	Front bumper clips <i>new</i>		30.00	✓
4	1 set	Front support panel top garnish clips <i>new</i>		30.00	✓
5	1 set	Front bonnet insulator clips <i>new</i>		30.00	✓
6	2 set	Front headlamp clips <i>new</i>	30.00	60.00	+
7	1 set	Front bumper lower cover clips <i>new</i>		30.00	+
8	1 set	Front radiator coolant <i>3M</i>		60.00	+
9	1 set	Front support panel sealants <i>1m</i>		60.00	+

80

**Labour charge**

Panel Beating		1,800.00	600
Spray painting		1,800.00	500
Check Wiring on headlamps and focussing		120.00	30
Anti rust		120.00	30
To remove and install condenser, top up gas		120.00	x.

1160

**\$ 25,174.10**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

total: 8756.08  
L/S: 67K.  
04 Days.

7K.