



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY  
3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

Ref: CS/GAI22001242/Aqf3q2

Date: 19/04/2022

Code: GAI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	XD 5775J	<b>Veh. Inspected</b>	YQ 5071B
<b>Policy No.</b>	MOMVC000008776-01-000	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CLMOMVC000004122	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	SHERY WONG	<b>Assign Date</b>	09/02/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HINO XZU710R	<b>c.c</b>	4009
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2021
<b>Chassis No.</b>	JHHUCV3FX0K041419	<b>Colour</b>	WHITE
<b>Odometer</b>	7956 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/85 R16	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	195/85 R16	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	195/85 R16	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	195/85 R16	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	08/02/2022	<b>Inspection Date</b>	11/02/2022
<b>Survey held at</b>	CHENG MOTOR WORK CO. NO.1 KAKI BUKIT AVE 6 #01-83 SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**