

# CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83  
 SINGAPORE 417883  
 Tel:65551185/6 Fax:65551184  
 H/P: 96713335  
 E-mail:chengmotor27@yahoo.com

*Xiao Chen*

11/2/2022

Great American Insurance Company.  
 3 Temasek Ave.  
 Singapore 039190  
 Attn: motor claims Dept

*JH HUCV3FXOK 041419*

Estimate cost of repair vehicle no: YQ5071B

1set Front Windsreen Rubber come with Glass <i>He m</i>		\$1642.90 +
Front Panel <i>Dented</i>		<del>1690.00</del> <i>985</i>
Front Grille <i>crack</i>	<i>1710</i>	<del>720.00</del> <i>654</i>
Front Grille LOGO <i>m</i>		<del>128.00</del> <i>71</i>
Front wiper Link <i>He m</i>	<i>1539</i>	487.90 +
S/nett		
Front HINO Sticker <i>He m</i>		78.00 ✓
Front 300 sticker <i>He m</i>	<i>3160</i>	58.00 ✓
Front Buddha Sticker <i>He m</i>		<del>480.00</del> <i>180</i>
ERP IU Bracket <i>He m</i>		35.00 x
Labour for knocking floor Panel,welding,cutting,repairing And replacement of parts.		<del>1000.00</del> <i>500</i>
To spray paint on the damage parts.		<del>1000.00</del> <i>400</i>
To dismantle and refit Dashboard	<i>1320</i>	<del>480.00</del> <i>220</i>
To dismantle and refit aircon system and refill gas		380.00 x
To dismantle and renew front windscreen rubber		<del>200.00</del> <i>120</i>
To check wiring		<del>80.00</del> <i>30</i>
To apply rust- proofing		<del>200.00</del> <i>50</i>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Adrian Lj*  
*L/S 11/02/22.*  
*04 Days.*  
*total: 3175.*  
*L/S: 2.5K.*

*2.5K*