

ASS. REC. BY: Steve

REF: CS/AG122001246/ETf3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD/TP/WS/TP RES/OD RES/EVA/INV/MY  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN/OUT

Veh No: 3MQ 90534 Yr Regn: 9/12/19  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: BMW 216i c.c. 1499  
Colour: white A/C: Insured / Std / NI / NA  
Sp. Reading: 30149 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: WBAGV190405P19380  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Modl: NII / S/Rim / STD A/Rim or  
Tyre Size: F: 205/60R16  
R: 11  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 4 mm R/Bal. 4 mm  
L/Bal. 4 mm L/Bal. 4 mm  
D.O.A. 3/12/22 D.O.I. 10/12/22  
Survey held at BIS Automobiles  
Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or  
Rear RH  
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>MV 106 K</u>
	<u>cost of repair of \$3172.20 (P/P before GST) - with 3 days of repair</u>
	<u>RED: 4156.60; 56%</u>

Date/Time, File Pass to?

☐ : Prel. Report  
☐ : Final Report

1) \_\_\_\_\_  
Date/Time, File Return to?

2) \_\_\_\_\_

Report Format : \_\_\_\_\_  
Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: 3  
Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:  
Transportation: \_\_\_\_\_  
S + RS: \$ \_\_\_\_\_  
Photos \_\_\_\_\_  
Others \_\_\_\_\_  
TOTAL \_\_\_\_\_

# BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927

BIS Automobiles Pte Ltd

Co. Reg. No. 201908617D GST Reg. No. 201908617D



## ESTIMATES

Estimate No. : 21998857  
Date Estimated : 08.02.2022  
Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -  
MR ANG WEE BOON

- ACCOUNT -  
AUTO & GENERAL INSURANCE  
190 Clemenceau Avenue  
#03-01  
Singapore Shopping Centre  
Singapore 239924  
Motor Claims Department

REGN. NO.	CHASSIS NO.	CC	MODEL
SMQ9053U	WBA6V120405P19380	1499	216
DESCRIPTION		ORIGINAL PRICE	NETT
To replace rear bumper and attachments include making good the tail end panel and knocking out dents caused by the accident		120	720 2,160.00
To spray paint the rear bumper and tail end panel			700 1,500.00
To transfer PDC assembly from old to new bumper include reconnecting to new bumper and conducting checks for proper function			120 150.00
To remove and install Rear boot compartment carpet and garnish to facilitate repairs			X 225.00
To carry out Diagnosis Tests - ABL			350 500.00
Sundries			60 100.00

DESCRIPTION		UNIT PRICE	QTY	NETT
51 12 7480322	Panel, bumper, primed, rear (Basis PDC) / 10	1035.00	1.00	1035.00
51 12 7403798	Flap, towing eye, primed / BR	43.25	1.00	43.25
51 12 7387278	Guide, bumper, side inner right	161.15	1.00	161.15
51 12 9477452	Set, mounts, PDC sensor, rear / MC	61.80	1.00	61.80
51 12 7396507	Left protection foil / MC	11.25	1.00	11.25
51 12 7396508	Right protection foil / MC	11.25	1.00	11.25
51 12 7372629	Support /	46.35	1.00	46.35
07 14 7155614	Hex nut with plate (M6) /	1.80	8.00	14.40
51 12 7318825	Carrier, bumper rear /	483.40	1.00	483.40
61 61 7360872	Rear reflector, rear right / BR	39.05	1.00	39.05

# BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927

BIS Automobiles Pte Ltd

Co. Reg. No. 201908617D. GST Reg. No. 201908617D



## ESTIMATES

66 20 9283750	Ultrasonic sensor Alpine White (U300) ?	383.15	12.00	766.30
66 20 9283203	Decoupling ring PDC torque n/c	5.15	4.00	20.60

Total Labour :	4635.00
Total Parts :	2693.80
Total Labour & Parts :	7328.80
Deduction for Excess :	
Total Repair Costs less Ex:	7328.80
GST @7%:	513.02
Grand Total :	7841.82

Steve (LKK)  
10/2/22, 11.00am  
83228813

MR PL  
PIP  
My BoL by  
3 dys

LKK	hence notify
the	following:
•	spray painting
•	(s) during resurvey
•	to confirmation
•	a "Without Prejudice" basis
•	(s) is allowed
•	must be resurveyed and
•	approval from Insurance Company
Approved by: Repairer	
Signature	
Date	