

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927

BIS Automobiles Pte Ltd

Co. Reg. No. 201908617D GST Reg. No. 201908617D



ESTIMATES

Estimate No. : 21998857
Date Estimated : 08.02.2022
Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -
MR ANG WEE BOON

- ACCOUNT -
AUTO & GENERAL INSURANCE
190 Clemenceau Avenue
#03-01
Singapore Shopping Centre
Singapore 239924
Motor Claims Department

REGN. NO.	CHASSIS NO.	CC	MODEL
SMQ9053U	WBA6V120405P19380	1499	216
DESCRIPTION		ORIGINAL PRICE	NETT
To replace rear bumper and attachments include making good the tail end panel and knocking out dents caused by the accident		120	720 2,160.00
To spray paint the rear bumper and tail end panel			700 1,500.00
To transfer PDC assembly from old to new bumper include reconnecting to new bumper and conducting checks for proper function			120 150.00
To remove and install Rear boot compartment carpet and garnish to facilitate repairs			X 225.00
To carry out Diagnosis Tests - ABL			350 500.00
Sundries			60 100.00

DESCRIPTION	UNIT PRICE	QTY	NETT
51 12 7480322 Panel, bumper, primed, rear (Basis PDC) / 11	1035.00	1.00	1035.00
51 12 7403798 Flap, towing eye, primed / BR	43.25	1.00	43.25
51 12 7387278 Guide, bumper, side inner right / x m	161.15	1.00	161.15
51 12 9477452 Set, mounts, PDC sensor, rear / APC	61.80	1.00	61.80
51 12 7396507 Left protection foil / APC	11.25	1.00	11.25
51 12 7396508 Right protection foil / APC	11.25	1.00	11.25
51 12 7372629 Support / x m	46.35	1.00	46.35
07 14 7155614 Hex nut with plate (M6) / x m	1.80	8.00	14.40
51 12 7318825 Carrier, bumper rear / x m	483.40	1.00	483.40
61 61 7360872 Rear reflector, rear right / BR	39.05	1.00	39.05

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927

BIS Automobiles Pte Ltd

Co. Reg. No. 201908617D. GST Reg. No. 201908617D



ESTIMATES

66 20 9283750	Ultrasonic sensor Alpine White (U300) ? Xnn	383.15	12.00	766.30
66 20 9283203	Decoupling ring PDC torque n/c	5.15	4.00	20.60

Total Labour :	4635.00
Total Parts :	2693.80
Total Labour & Parts :	7328.80
Deduction for Excess :	
Total Repair Costs less Ex:	7328.80
GST @7%:	513.02
Grand Total :	7841.82

Steve (LKK)
10/2/22, 11.00am
83228813

Mr PL
PIP
My BoL by
3 djs

LKK	hence notify
the	following:
•	spray painting
•	(s) during resurvey
•	to confirmation
•	a "Without Prejudice" basis
•	(s) is allowed
•	must be resurveyed and
•	approval from Insurance Company
Approved by: Repairer	
Signature	
Date	