

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Accident Date : 06.02.2022

*Not Notified
 U Reg @
 Pursuing After Paint*

Sclays Third Party
 Policy No: _____

Date: 08.02.2022

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Hyundai Elantra" Reg No. SKT5386T Claiming Against Your Insured Veh. No. SLL8806J			
1pc	Boot		<i>Rn</i> 1,650.20 ✓
2pcs	Boot Hinges	102.00	<i>R</i> 204.00 X
1pc	Boot Emblem		<i>Rn</i> 32.00 ✓
1pc	Boot Badge Elantra		<i>Rn</i> 56.00 ✓
1pc	Boot Badge Elite		<i>Rn</i> 73.00 ✓
1pc	Boot Lamp LH		<i>CMA</i> 340.00 ✓
1pc	Boot Lamp Gasket LH		<i>Rn</i> 26.00 ✓
1pc	Boot Lock		<i>Rn</i> 133.00 ✓
1pc	Boot Lock Catch		<i>R</i> 18.90 X
1pc	Boot Weatherstrip		<i>Not Notified</i> 106.00 <i>502m</i>
1pc	Boot Trim Board		<i>CMA</i> 93.00 ✓
1pc	Boot Stopper		<i>mt</i> 12.50 ✓
12pcs	Boot Trim Board Clips	3.00	<i>Rn</i> 36.00 ✓
1pc	Boot Remote Opener Sensor		<i>CMA</i> 265.00 ✓
1pc	Rear Bumper		<i>CMA</i> 527.00 ✓
12pcs	Rear Bumper Clips	3.00	<i>Rn</i> 36.00 ✓
2pcs	Rear Bumper Brackets	42.00	84.00 ?
1pc	Rear Bumper Reinforcement		<i>CMA</i> 320.00 ✓
3pcs	Rear Bumper Lower Retainers	51.00	153.00 ?
2pcs	Rear Bumper Top Retainers	55.00	110.00 ?
1pc	Rear Bumper Lower Lip		<i>CMA</i> 90.30 ✓
2pcs	Rear Bumper Reflectors	<i>NS CMA</i> 30.00	60.00 ✓
1pc	Rear Bumper Corner Retainer LH		<i>Rn</i> 19.00 X
1pc	Rear Bumper Inner Boot Key Sensor		<i>CMA</i> 245.00 ✓
1pc	End Panel		<i>Rn</i> 447.00 ✓
1pc	End Panel Garnish		<i>mt CMA</i> 69.00 ✓
1pc	Rear Fender Trim Board LH		<i>CMA</i> 215.00 ✓
1pc	Spare Tyre Top Board		<i>Rn</i> 279.00 X
	Less 20%		5,699.90
	Rear Bumper Reverse Sensor		1,139.98
	Rear Number Plate		4,559.92
	To Dismantle / Transfer Boot Fittings / Ancillary Accessories by Repairer		<i>PCR</i> 280.00 SN
	To Conduct Rear Electrical Check, Replace Reverse Sensors, Module, Rewiring etc		<i>Net</i> 45.00 SN
			80.00 <i>50</i>
			120.00 <i>50</i>
		C/F	5,084.92

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Amount Unit Price

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0496007-A0

To: India International Insurance Pte Ltd

Accident Date : 06.02.2022

Policy No: Third Party

 Date: 08.02.2022

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Hyundai Elantra" Reg No. SKT5386T Claiming Against Your Insured Veh. No. SLL8806J		
		B/F	5,084.92
	To Supply End Panel Body Sealant		60.00 <i>302</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 <i>601</i>
	To Dismantle / Refit Trunk Compartment Boards & Trims		1,000.00 <i>601</i>
	Labour Charge - Panel Beating, Repairing Rear Chassis Member, Inner Panel, Spare Tyre Panel etc. Cnt, Weld End Panel And Parts Replacement		1,200.00 <i>600</i>
	To Spray Paint Affected Areas		850.00 <i>600</i>
		Total :	8,294.92

LK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: