



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN: ONG KIAN THENG DERICK

Ref: CS/ASM22001254/Vty3e2  
Date: 19/05/2022  
Code: ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHA 9568U	<b>Veh. Inspected</b>	SLS 8731D
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S2M03SWG	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ONG KIAN THENG DERICK	<b>Assign Date</b>	09/02/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HYUNDAI ELANTRA GLS	<b>c.c</b>	1591
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	KMHD841CMJU515801	<b>Colour</b>	BLUE
<b>Odometer</b>	89934 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/65 R15	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	195/65 R15	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	195/65 R15	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	195/65 R15	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	23/04/2021	<b>Inspection Date</b>	10/02/2022
<b>Survey held at</b>	SPEEDWERKZ PTE LTD 13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>2 Working Days</b>
--	-----------------------