



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE			Ref: CC4/ASM22001256/Apa3q2 Date: 18/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 3347U	Veh. Inspected	SLV 3901Y
	Policy No.	P2465679	Coverage (\$)	0.00
	Claim No.	S2M03SSM	Excess (\$)	0.00
	Assign From		Assign Date	09/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL HYBRID	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	RU31265193	Colour	WHITE
	Odometer	83400 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	KAPSEN	6 mm
	L/H Front Tyre	215/60 R16	KAPSEN	6 mm
	R/H Rear Tyre	215/60 R16	KAPSEN	6 mm
	L/H Rear Tyre	215/60 R16	KAPSEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/01/2022	Inspection Date	09/02/2022
	Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	