

# PHILIP LIAISON AUTOMOBILES

(3555)

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0082/2022/JT  
DATE : 7-Feb-22  
WIP : 10411

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LIEW MUN KIONG  
ADDRESS : 50 AMBER ROAD  
#12-01  
SINGAPORE 439888  
TELEPHONE : HP +65 87818438  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 7210074983  
VEHICLE NO : SMQ 8218 T  
MODEL CODE : AUDI Q3 SB 1.4 TFSI  
MODEL YEAR : 28/7/2021  
ENGINE NO : CZD C41672  
CHASSIS NO : WAUZZZF30M1128013  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 4-Feb-22  
PLACE OF ACCIDENT : 238 THOMSON ROAD CAR PARK

# PREMIUM AUTOMOBILES

(111)

DEPENDENT ON THE WORK DONE  
THE QUOTE IS FOR THE WORK DONE  
AND THE PARTS USED. THE QUOTE IS FOR THE WORK DONE  
AND THE PARTS USED. THE QUOTE IS FOR THE WORK DONE  
AND THE PARTS USED.

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMO 8218 T

| S/N                  | NATURE OF JOBS                                                                                                                                                       | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|----------------------------|
| 1                    | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.                     | S/N \$ 480.00     | ✓                          |
| 2                    | TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                                                | S/N \$ 400.00     | 250                        |
| 3                    | TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.                             | S/N \$ 280.00     | ✓                          |
| 4                    | TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER LHS HEADLIGHT. TO REPAIR LHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 2,800.00       | 1500 ✓                     |
| 5                    | TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR, TWO DOOR COVERS AND BOTH FRONT WHEEL ARCH TRIMS.               | \$ 6,000.00       | 2450 ✓                     |
| 6                    | TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.                                                                                                                | S/N \$ 280.00     | XNN                        |
| 7                    | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                       | S/N \$ 192.00     | ✓                          |
| TOTAL LABOUR CHARGES |                                                                                                                                                                      | \$ 10,432.00      |                            |



MATERIAL LIST FOR ACCIDENT VEHICLE REGN.NO. SMQ 8218 T

| S/N                   | PARTS DESCRIPTION                          | QTY | UNIT PRICE  | SINNET  | REMARKS |
|-----------------------|--------------------------------------------|-----|-------------|---------|---------|
| 1                     | FRONT BUMPER - LH                          | 1   | \$ 1,423.00 | /Scr    | 1138.40 |
| 2                     | FRONT BUMPER FIXING PARTS                  | 1   | \$ 433.00   | XNN     |         |
| 3                     | FRONT BUMPER CLOSING ELEMENT - LH          | 1   | \$ 66.00    | ? X     | SVC     |
| 4                     | FRONT BUMPER CLOSING ELEMENT END PLATE     | 1   | \$ 212.00   | ? X     | SVC     |
| 5                     | FRONT BUMPER SPOILER                       | 1   | \$ 850.00   | /Scr    | 679.60  |
| 6                     | FRONT BUMPER BRACKET                       | 1   | \$ 24.00    | /n/c    | 18.56   |
| 7                     | FRONT BUMPER AIR GUIDE GRILLE - LH         | 1   | \$ 171.00   | Xs/c    |         |
| 8                     | FRONT BUMPER TRIM - LH                     | 1   | \$ 182.00   | Xs/c    |         |
| 9                     | FRONT PARKING AID SENSOR SUPPORT - LH      | 1   | \$ 29.00    | /n/c    | 22.72   |
| 10                    | FRONT BUMPER GUIDE SECTION - LH            | 1   | \$ 43.00    | Xs/c    |         |
| 11                    | FRONT BUMPER TOP COVER                     | 1   | \$ 137.00   | Xs/c    |         |
| 12                    | CAUTION STICKER                            | 1   | \$ 16.00    | Xs/c    |         |
| 13                    | AIR COND STICKER                           | 1   | \$ 9.00     | Xs/c    |         |
| 14                    | FRONT FENDER - LH                          | 1   | \$ 1,445.00 | /Dr     | 1156    |
| 15                    | FRONT FENDER ATTACHMENT PARTS              | 1   | \$ 66.00    | XNN     |         |
| 16                    | FRONT FENDER BRACE - LH                    | 1   | \$ 98.00    | ? 77.68 | nec     |
| 17                    | FRONT FENDER BRACKET - LH                  | 1   | \$ 39.00    | ? 30.48 | nec     |
| 18                    | FRONT FENDER CLOSING ELEMENT - LH          | 1   | \$ 37.00    | ? X     | SVC     |
| 19                    | FRONT WHEEL HOUSING LINER - LH             | 1   | \$ 260.00   | XNN     |         |
| 20                    | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS | 1   | \$ 105.00   | XNN     |         |
| SUB TOTAL SPARE PARTS |                                            |     | \$ 5,645.00 |         |         |

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTO MOBILES

REGISTERED ELECTRICAL ENGINEER  
TEL: 0800 222 777 FAX: 0800 111 111  
EMAIL: info@premiumautomobiles.co.nz

## REPAIR LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 8218 T

|                      |                                      |     |             | DAMAGED PARTS & PRICES |  |
|----------------------|--------------------------------------|-----|-------------|------------------------|--|
| S/N                  | PARTS DESCRIPTION                    | QTY | S/NETT      | REMARKS                |  |
| 21                   | FRONT WHEEL HOUSING LINER COVER - LH | 1   | \$ 18.00    | XNN                    |  |
| 22                   | HEADLIGHT MOUNTING - LH              | 1   | \$ 132.00   | 7. X SVC               |  |
| 23                   | HEADLIGHT - LH                       | 1   | \$ 5,952.00 | Scr 4761.60            |  |
| 24                   | LIFT CYLINDER - LH                   | 1   | \$ 231.00   | 7. X SVC               |  |
| 25                   | LIFT CYLINDER HOSE - LH              | 1   | \$ 92.00    | 7. X SVC               |  |
| 26                   | FRONT WHEEL ARCH COVER - LH / RH     | 2   | \$ 1,132.00 | 7. 904.80 cut          |  |
| 27                   | FRONT DOOR COVER - LH                | 1   | \$ 390.00   | XNN                    |  |
| 28                   | REAR DOOR COVER - LH                 | 1   | \$ 368.00   | XNN                    |  |
| 29                   | ALUMINIUM RIM                        | 1   | \$ 1,414.00 | X SVC                  |  |
| 30                   | SUNDRIES                             |     | \$ 400.00   | XNN                    |  |
| TOTAL SPARE PARTS    |                                      |     | :           | \$ 15,774.00           |  |
| TOTAL LABOUR CHARGES |                                      |     | :           | \$ 10,432.00           |  |
| GRAND TOTAL          |                                      |     | :           | \$ 26,206.00           |  |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

NAME  
SURVEYED DATE  
AUTHORISED DATE  
EXCESS COST  
LIABILITY  
REMARKS

Thuan@Lthayto.com  
82235769  
8/2/20 1 630  
P/P excess: TBC  
5 days wp

**PLEASE NOTE**

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT