

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Tokio Marine Insurance Singapore Ltd
20 McCallum Street, #09-01 Tokio Marine Centre
Singapore 069046

Our File No: CS4/TMI22001265/KTF3E2

Date: 07/04/2022

REFERENCE

Insured/Claimant: Loh Ngai Lung (Luo Yineng) Policy No: MK000435
Date of Loss: 07/02/2022 Nature of Claim: OD Claim No: M2200693

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCG3021Y**
Make & Model: VOLKSWAGEN BEETLE 1300, 1.3 (M) Engine No: F1597584
Reg. Date: 06/05/1969 (Man. Year: 1969) Chassis No: 119521736
Colour: Metallic Green/White Odometer: 0 km
Engine Capacity: 1300 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11.00	11.00	0.00	0.00
+ GST 7.00/0.00% (S\$)	0.77	0.00	0.77	100.00
Nett Amount (S\$)	11.77	11.00	0.77	6.54

INSPECTION

Date of Assignment: 10/02/2022 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 10/02/2022 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$46,000 - \$50,000
OMV : \$0.00
PARF Rebate (1) : \$0.00
Quota Premium Paid : \$26,175.00
COE Rebate (2) : \$18,911.00
Total Rebate (1) + (2) = : \$18,911.00

The total amount incurred will be Market Value \$46,000 - \$50,000 minus Total Rebate \$18,911.00 = \$27,089.00 - \$31,089.00

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2022)

Parts: 144 VOLKSWAGEN BEETLE 1300 1.3 (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SCG3021Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<hr/>				
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
<hr/>				
			Sub Total (\$\$)	11.00
<hr/>				

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >