



Your Ref : M2200693

Date: 07th Apr 2022

Our Ref : CS4/TMI22001265/Ktf3e2

M/s Tokio Marine Insurance Singapore Ltd

20 Mccallum Street #09-01

Tokio Marine Centre

Singapore 069046

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SCG 3021Y
ACCIDENT ON 07/02/2022**

Instruction was received to inspect the vehicle Reg. No. SCG 3021Y. The inspection was conducted on 10/02/2022 at the premises of M/s Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming), 160 Sin Ming Drive #04-01, Sin Ming AutoCity, Singapore 575722.

The following vehicle information was recorded:

Registration Number : SCG 3021Y
Make/Model : Volkswagen 1300
Year of Registration : 1969
Body Colour : Metallic Green / White
Chassis Number : 119521736
Engine Capacity : 1300 cc

The vehicle caught fire. The cause of fire probably due to short circuit at the engine compartment. (Details see photographs enclosed)



In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 46,000.00 - \$50,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 18,911.00)
Nett Liability	<u>S\$ 27,089.00 - \$31,089.00</u> =====

Vehicle Inspected By:

KONG SENG CHEONG
Licensed Appraiser

K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIAd, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.