

2 Kaki Bukit Ave 2, #02-19/22 AutoHub Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

JN1JANT322002567.

ESTIMATE OF REPAIR

Veh# : SLG7909D

DOA : 9/2/2022

Location : PIE TOWARDS CHANGI AT TOA PAYOH EXIT

TP Alb.
Xiao Tong

Model:

NISSAN X-TRAIL
25/11/2016

3P:

SKB6744G(AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Rehnd</i>			811.00
2	16 pcs	Rear bumper clips <i>Neu</i>		30.00	✓
3	1 pc	Rear bumper enforcement <i>Dented</i>			693.90 569.
4	2 pcs	Rear bumper o/s & n/s reflector <i>Not in</i>			120.60
5	1 pc	Rear bumper diffuser <i>Not in</i>			136.50
6	1 pc	Rear tailgate <i>Cracked</i>			4200.00 ✓
7	1 pc	Rear tailgate lock <i>Damaged</i>			570.00 ✓
8	1 pc	Rear tailgate lock handle <i>Neu</i>			75.60
9	1 pc	Rear tailgate inner garnish <i>Cracked</i>			588.40 452.
10	2 pcs	Rear o/s & n/s shock absorber <i>3 x 1</i>			2430.60
11	2 pcs	Rear o/s & n/s tail gate sensor <i>1 neu</i>			1020.40
12	2 pcs	Rear o/s & n/s tail lamp <i>3 x 1</i>			865.40
13	2 pcs	Rear o/s & n/s reflector <i>1 neu</i>			560.00
14	1 pc	Rear end panel <i>Reps</i>			526.40
15	1 pc	Rear end panel inner trim <i>Neu</i>			310.20
16	1 pc	Rear end panel metal plate <i>Not in</i>			125.60
17	1 pc	Rear buzzer <i>Neu</i>			265.50
18	1 pc	Rear 'X-Trail' emblem <i>3 neu</i>			78.00
19	1 pc	Rear 'Nissan' emblem <i>1 neu</i>			91.00
20	4 pcs	Rear reverse sensor <i>Damaged 2 pieces</i>			1380.00 50520
21	1 pc	Rear windscreen moulding <i>Neu</i>		160.00	✓
22	1 pc	windscreen sealant <i>Neu</i>		80.00 60	
23	2 pcs	Rear o/s & n/s fender inner trim <i>3 x 1</i>			
24	2 pcs	Rear o/s & n/s wheel arch garnish <i>1 neu</i>			465.40
25	2 pcs	Rear o/s & n/s bumper stay <i>Not in</i>			164.20
26	2 pcs	Rear end panel o/s & n/s (cardboard garnish) <i>Not in</i>			315.60
27	1 pc	Rear bumper centre garnish (black) <i>Not in</i>			96.50
28	1 pc	Rear n/s & o/s end panel enforcement stay <i>Not in</i>			432.60
29	1 pc	Rear regn. Plate <i>3 x 1</i>		28.00	✓
30	1 pc	Rear regn. Bracket <i>3 x 1</i>		30.00	✓
			0.00	328.00	16,323.40
			30%	0%	10%
After Less %:			0.00	328.00	14691.06
Labour					
1		To dismantle, refit, repair & realign damaged parts	1,400.00		500
2		To spray painting	1,200.00		500
3		To remove and refit rear windscreen	180.00		120.
4		To remove and replace rear tail-gate (Mechanism).	150.00		80
5		To remove and refit rear reverse camera	80.00		50
6		To re-set electrical system.	180.00		30
7		To re-seal anti-rust	80.00		40
8		To check wiring	60.00		30
Sub-Total:				3,330.00	
Total:				18,349.06	
Total:				14,679.25	

693
569.
452.
7173
645570
S.N: 250.

Adrian L
L/S 10/02/22

1350

Total: 8055.70
L/S: 6.4K.
04 Days.

Chan
Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

LKK Auto Consultants Member since 2004

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: *[Signature]*
Date: _____

