

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

Tel :9695 5547 Fax: 6481 5727 e-mail : evelynngstrading@gmail.com

Reg No: 201812604N

10/2/2022

Ergo Insurance Pte Ltd
5 Temasek Boulevard
Singapore 038985
Attn: Motor Claims Dept

Not withstanding
61Ry & 155dp
Newly After Paint
4days

RE: Accident On 21/01/2022 @14:30Hrs
Along Moonbeam Walk, Involving SJT3199S & YN2641S
Claims Against YN2641s
Your Claim Ref: CDMCG22000154

We submit herewith our direct claim estimate quotation as follow:-
Replacement parts - Toyota Vios

1	Frt Bumper		CM	\$	447.90	✓
1	Frt Bumper Retainer LH			\$	56.50	✓
1	Cover, Frt Bumper Fog Lamp LH			\$	80.81	X
1	Bonnet		R	\$	465.17	✓
2	Frt bumper side retainer RH/LH	Repair	\$	48.16	\$	96.32 X
20	Clips, Fender liner		\$	3.50	\$	70.00 X
1	Frt logo "Badge"	S.nett			\$	45.30 ✓
1	Support panel				\$	256.70 X
1	Brace panel				\$	43.00 X
1	Frt Bumper Grille Lower				\$	56.00 X
1	Radiator Grill				\$	138.90 ✓
1	No plat	\$40 s. nett Rd ✓				
To remove frt damaged part with all necessary component/attachn.				\$	600.00	500
Straighten chassis member, repair/reshape dented body panel..						
Replace damaged part. Refit into position.						
To spray painting -				\$	600.00	550
Check wiring & light function				\$	50.00	20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Any other parts which necessitate repair or renewal will incur additional charged.
Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully.

NGS MOTORSPORT PTE LTD
EVELYN NG

\$ 3,006.60

3046.60