4	1 of 2?	>	Þ١	\bigcirc	Θ	100%	~		ф	Find Next	
---	---------	---	----	------------	----------	------	---	--	---	-------------	--



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	ale Des Experts En	Automob	ile			
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22001269/Vvf3			
	300 BEACH ROAD #17-04/07 THE CO) NCOURSESINGAPORE 199555		Date:	10/02/2022			
				Code:	LPC2			
1.		Policy Particulars :-	(THIRD PARTY	CLAIM				
	Insured Veh.	GBE 5965H	Veh. Inspected	l	PC 1949B			
	Policy No.		Coverage (\$)		0.00			
	Claim No.	22/22/22/VC05/025437	Excess (\$)		0.00			
	Assign From	GERALD POH	Assign Date		10/02/2022			
2.		Vehicle Partic	ulars & Condition	on				
	Make & Model		c.c		0			
	Engine No.	HIDDEN	Year of Reg.					
	Chassis No.		Colour					
	Odometer	-	Steering					
	Brakes		Modification					
	General							
3.		Condition	ons of Tyres					
		Size	Make		Balance			
	R/H Front Tyre				mm			
	L/H Front Tyre				mm			
	R/H Rear Tyre				mm			
	L/H Rear Tyre				mm			
4.		Descriptio	n of Damages					
5.			Information					
	Accident Date	08/02/2022	Inspection Dat	e	23/02/2022			
	Survey held at	A-TEC AUTOMOTIVE PTE LTD						
		8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875						
5a.	l .	Re	marks					
	B) THE REPAIR ES	ON WAS CONDUCTED ON A "WI" STIMATE WAS NOT PRESENTED IAS TOLD TO PREPARE THE EST EASE FIND DAMAGED VEHICLE	AT THE TIME OF IMATE.	INSPEC				