



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2203739

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 16/06/2022  
Reference CC6/CTI22001270/Ega3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SLQ 7063R  
Insured Veh. SJZ 7890X  
Claim No. SNM22D201104  
Policy No. DMPCSNA00262132101  
Accident Date 08/02/2022  
Inspection Date 10/02/2022

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (7%)</b>                | <b>28.00</b>  |
| <b>Grand Total</b>             | <b>428.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                 |                 |                                                              |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|-----------------|--------------------------------------------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                         |                                                                                                 |                 | Ref: CC6/CTI22001270/Ega3q2<br>Date: 16/06/2022<br>Code: CTI |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                 |                 |                                                              |  |
| Insured Veh.                                                                                                                           | SJZ 7890X                                                                                       | Veh. Inspected  | SLQ 7063R                                                    |  |
| Policy No.                                                                                                                             | DMPCSN00262132101                                                                               | Coverage (\$)   | 0.00                                                         |  |
| Claim No.                                                                                                                              | SNM22D201104                                                                                    | Excess (\$)     | 0.00                                                         |  |
| Assign From                                                                                                                            |                                                                                                 | Assign Date     | 10/02/2022                                                   |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                 |                 |                                                              |  |
| Make & Model                                                                                                                           | HONDA FREED                                                                                     | c.c             | 1496                                                         |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                          | Year of Reg.    | 2017                                                         |  |
| Chassis No.                                                                                                                            | GB71029955                                                                                      | Colour          | BLUE                                                         |  |
| Odometer                                                                                                                               | 123208 KM                                                                                       | Steering        | IN ORDER                                                     |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                        | Modification    | SPORTS RIM                                                   |  |
| General                                                                                                                                | GOOD                                                                                            |                 |                                                              |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                 |                 |                                                              |  |
|                                                                                                                                        | Size                                                                                            | Make            | Balance                                                      |  |
| R/H Front Tyre                                                                                                                         | 195/60 R15                                                                                      | DUNLOP          | 4 mm                                                         |  |
| L/H Front Tyre                                                                                                                         | 195/60 R15                                                                                      | DUNLOP          | 4 mm                                                         |  |
| R/H Rear Tyre                                                                                                                          | 195/60 R15                                                                                      | DUNLOP          | 4 mm                                                         |  |
| L/H Rear Tyre                                                                                                                          | 195/60 R15                                                                                      | DUNLOP          | 4 mm                                                         |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                 |                 |                                                              |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                                                 |                 |                                                              |  |
| <b>5. General Information</b>                                                                                                          |                                                                                                 |                 |                                                              |  |
| Accident Date                                                                                                                          | 08/02/2022                                                                                      | Inspection Date | 10/02/2022                                                   |  |
| Survey held at                                                                                                                         | AUTOMOTIVE REPAIR CENTRE PTE LTD<br>38 WOODLANDS INDUSTRIAL PARK E1 # 05-18<br>SINGAPORE 757700 |                 |                                                              |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                 |                 |                                                              |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                 |                 |                                                              |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                                 |                 |                                                              |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                 |                 | 4 Working Days                                               |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 7063R

| Qty | Description of Parts                      | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>        |                      |                           |                   |
| 1   | REAR BUMPER                               | DENTED               | 1,250.00                  | 828.00            |
| 10  | REAR BUMPER CLIPS @\$6.00                 | NECESSARY            | 60.00                     | 30.00             |
| 1   | REAR BUMPER UPPER RETAINER RH             | BROKEN               | 30.00                     | 30.00             |
| 1   | REAR BUMPER UPPER RETAINER LH             | BROKEN               | 30.00                     | 30.00             |
| 1   | REAR BUMPER LOWER RETAINER RH             | NOT NECESSARY        | 40.00                     | -                 |
| 1   | REAR BUMPER LOWER RETAINER LH             | NOT NECESSARY        | 40.00                     | -                 |
| 1   | REAR BUMPER TOW EYE COVER                 | NOT NECESSARY        | 30.00                     | -                 |
| 1   | REAR BUMPER REFLECTOR RH                  | NOT NECESSARY        | 60.00                     | -                 |
| 1   | REAR BUMPER REFLECTOR LH                  | NOT NECESSARY        | 60.00                     | -                 |
| 1   | REAR TAILGATE                             | DENTED               | 1,000.00                  | 1,000.00          |
| 1   | REAR TAILGATE RUBBER SEAL                 | NECESSARY            | 120.00                    | 120.00            |
| 1   | REAR TAILGATE CHROME GARNISH              | NOT NECESSARY        | 240.00                    | -                 |
| 2   | REAR TAILGATE LICENSE PLATE LAMP @\$60.00 | NOT NECESSARY        | 120.00                    | -                 |
| 1   | REAR TAILGATE FREED EMBLEM                | NECESSARY            | 60.00                     | 60.00             |
| 1   | REAR TAILGATE HYBRID EMBLEM               | NECESSARY            | 70.00                     | 70.00             |
| 1   | REAR TAILGATE LOCK ASSY                   | NOT NECESSARY        | 100.00                    | -                 |
| 1   | REAR TAILGATE LOCK COVER                  | NOT NECESSARY        | 40.00                     | -                 |
| 1   | REAR TAILGATE LOCK LATCH                  | NOT NECESSARY        | 40.00                     | -                 |
| 1   | REAR TAILGATE INNER TRIM                  | NOT NECESSARY        | 300.00                    | -                 |
| 1   | REAR TAILGATE INNER TRIM RH COVER         | NOT NECESSARY        | 60.00                     | -                 |
| 1   | REAR TAILGATE INNER TRIM BOTTOM COVER     | NOT NECESSARY        | 30.00                     | -                 |
| 1   | REAR TAILGATE INNER TRIM LH COVER         | NOT NECESSARY        | 60.00                     | -                 |
| 1   | REAR/ END PANEL SIDE GARNISH              | NOT NECESSARY        | 80.00                     | -                 |
| 1   | REAR/ END PANEL GARNISH COVER             | NOT NECESSARY        | 150.00                    | -                 |
| 1   | END PANEL                                 | TO REPAIR SEE LABOUR | 450.00                    | -                 |
| 1   | REAR TAILGATE HONDA EMBLEM                | NECESSARY            | 50.00                     | 50.00             |
|     | LESS 20% DISCOUNT                         |                      | -                         | -443.60           |
|     |                                           |                      | 4,570.00                  | 1,774.40          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>          |                      |                           |                   |
| 1   | REAR WINDSCREEN SEALANT (SN)              | NECESSARY            | 40.00                     | 40.00             |

Report Ref No. CC6/CTI22001270/Ega3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                | Description of Parts                                                                 | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|--------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1                  | SUPPLY AND INSTALLATION OF SOLAR FILM (SN)                                           | NOT NECESSARY | 280.00                    | -                 |
| 2                  | REVERSE SENSOR @\$200.00 (SN)                                                        | SHORTED       | 400.00                    | 200.00            |
|                    |                                                                                      |               | 720.00                    | 240.00            |
|                    | <b>LABOUR</b>                                                                        |               |                           |                   |
|                    | SPRAY PAINTING REAR BUMPER ,TAILGATE ,FENDERS & INNER PANELS.                        |               | 1,000.00                  | 600.00            |
|                    | REMOVE,REPLACE ,REPAIR AND REFIT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF END PANEL. |               | 1,200.00                  | 500.00            |
|                    | TRANSFER DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR.                              |               | 100.00                    | 50.00             |
|                    | REMOVE AND REFIT REAR WINDSCREEN.                                                    |               | 150.00                    | 120.00            |
|                    | REMOVE AND REFIT REAR REVERSE SENSOR .                                               |               | 160.00                    | 30.00             |
|                    | APPLY RUST PROOFING ON REPLACED /REPAIRED PANEL.                                     |               | 100.00                    | 30.00             |
|                    | CHECK AND RECTIFY ELECTRICAL WIRING.                                                 |               | 30.00                     | 30.00             |
|                    |                                                                                      |               | 2,740.00                  | 1,360.00          |
| <b>GRAND TOTAL</b> |                                                                                      |               | <b>8,030.00</b>           | <b>3,374.40</b>   |

|                                                                             |  |  |                 |
|-----------------------------------------------------------------------------|--|--|-----------------|
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |  |  | <b>2,700.00</b> |
|-----------------------------------------------------------------------------|--|--|-----------------|

Report Ref No. CC6/CTI22001270/Ega3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLQ 7063R

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLQ 7063R

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLQ 7063R

RE-INSPECTION

