

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C  
GST Reg. No. : 201312913C

**Estimate**

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2202-078-TG

DATE : 9-Feb-2022

POLICY NO. : P10410802R01

VEHICLE REG. NO. : **SLQ7063R**

VEHICLE MAKE : HONDA FREED HYBRID 1.5G 2017

TO Motor Claim Department

**China Taiping Insurance (Singapore) Pte. Ltd**

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<b><u>SPARE PARTS</u></b>			
1	Rear Bumper	1	\$ 1,250.00	\$ 1,250.00
2	Rear Bumper Clips	10	\$ 6.00	\$ 60.00
3	Rear Bumper Upper Retainer RH	1	\$ 30.00	\$ 30.00
4	Rear Bumper Upper Retainer LH	1	\$ 30.00	\$ 30.00
5	Rear Bumper Lower Retainer RH	1	\$ 40.00	\$ 40.00
6	Rear Bumper Lower Retainer LH	1	\$ 40.00	\$ 40.00
7	Rear Bumper Tow Eye Cover	1	\$ 30.00	\$ 30.00
8	Rear Bumper Reflector RH	1	\$ 60.00	\$ 60.00
9	Rear Bumper Reflector LH	1	\$ 60.00	\$ 60.00
10	Rear Tailgate	1	\$ 1,000.00	\$ 1,000.00
11	Rear Tailgate Rubber Seal	1	\$ 120.00	\$ 120.00
12	Rear Tailgate Chrome Garnish	1	\$ 240.00	\$ 240.00
13	Rear Tailgate License Plate Lamp	2	\$ 60.00	\$ 120.00
14	Rear Tailgate Honda Emblem	1	\$ 50.00	\$ 50.00
15	Rear Tailgate Freed Emblem	1	\$ 60.00	\$ 60.00
16	Rear Tailgate Hybrid Emblem	1	\$ 70.00	\$ 70.00
17	Rear Tailgate Lock Assy	1	\$ 100.00	\$ 100.00
18	Rear Tailgate Lock Cover	1	\$ 40.00	\$ 40.00
19	Rear Tailgate Lock Latch	1	\$ 40.00	\$ 40.00
20	Rear Tailgate Inner Trim	1	\$ 300.00	\$ 300.00
21	Rear Tailgate Inner Trim RH Cover	1	\$ 60.00	\$ 60.00
22	Rear Tailgate Inner Trim Bottom Cover	1	\$ 30.00	\$ 30.00
23	Rear Tailgate Inner Trim LH Cover	1	\$ 60.00	\$ 60.00
24	Rear / End Panel Side Garnish	1	\$ 80.00	\$ 80.00
25	Rear / End Panel Garnish Cover	1	\$ 150.00	\$ 150.00
26	End Panel	1	\$ 450.00	\$ 450.00
			<b>Total Spare Parts</b>	<b>\$ 4,570.00</b>

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

**Estimate**

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2202-078-TG

DATE : 9-Feb-2022

POLICY NO. : P10410802R01

VEHICLE REG. NO. : **SLQ7063R**

VEHICLE MAKE : HONDA FREED HYBRID 1.5G 2017

**TO** Motor Claim Department**China Taiping Insurance (Singapore) Pte. Ltd**

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

**FOR SURVEYOR****ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<b><u>SPECIAL NETT</u></b>			
27	Rear Windscreen Sealant	1	\$ 40.00	\$ 40.00
28	Supply and Installation of Solar film	1	\$ 280.00	\$ 280.00
29	Reverse Sensor	2	\$ 200.00	\$ 400.00
<b>Total Special Nett</b>				<b>\$ 720.00</b>
	<b><u>LABOUR</u></b>			
30	Spray painting Rear Bumper, Tailgate, Fenders & Inner Panels	1	\$ 1,000.00	\$ 1,000.00
31	Remove, Replace, Repair and Refit Affected Area	1	\$ 1,200.00	\$ 1,200.00
32	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 100.00	\$ 100.00
33	Remove and Refit Rear Windscreen	1	\$ 150.00	\$ 150.00
34	Remove and Refit Rear Reverse Sensor	2	\$ 80.00	\$ 160.00
35	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
36	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
<b>Total Labour</b>				<b>\$ 2,740.00</b>
<b>Amount Before Excess</b>				<b>\$ 8,030.00</b>
<b>Add GST @ 7%</b>				<b>562.10</b>
<b>Total Amount Payable</b>				<b>\$ 8,592.10</b>

**Estimate prepared by: RAZALI**

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.