

ARC**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2202-078-TG

DATE : 9-Feb-2022

POLICY NO. : P10410802R01

VEHICLE REG. NO. : SLQ7063R

VEHICLE MAKE : HONDA FREED HYBRID 1.5G 2017

FOR SURVEYOR

TO Motor Claim Department
 China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper / DD	1	\$ 1,250.00	\$ 1,250.00
2	Rear Bumper Clips / MC	10	\$ 6.00	\$ 30 / 60.00
3	Rear Bumper Upper Retainer RH / GR	1	\$ 30.00	\$ 30.00
4	Rear Bumper Upper Retainer LH / GR	1	\$ 30.00	\$ 30.00
5	Rear Bumper Lower Retainer RH X NN	1	\$ 40.00	\$ 40.00
6	Rear Bumper Lower Retainer LH X NN	1	\$ 40.00	\$ 40.00
7	Rear Bumper Tow Eye Cover X NN	1	\$ 30.00	\$ 30.00
8	Rear Bumper Reflector RH X NN	1	\$ 60.00	\$ 60.00
9	Rear Bumper Reflector LH X NN	1	\$ 60.00	\$ 60.00
10	Rear Tailgate / DD	1	\$ 1,000.00	\$ 1,000.00
11	Rear Tailgate Rubber Seal / MC	1	\$ 120.00	\$ 120.00
12	Rear Tailgate Chrome Garnish X NN	1	\$ 240.00	\$ 240.00
13	Rear Tailgate License Plate Lamp X NN	2	\$ 60.00	\$ 120.00
14	Rear Tailgate Honda Emblem / MC	1	\$ 50.00	\$ 50.00
15	Rear Tailgate Freed Emblem / MC	1	\$ 60.00	\$ 60.00
16	Rear Tailgate Hybrid Emblem / MC	1	\$ 70.00	\$ 70.00
17	Rear Tailgate Lock Assy ? X NN	1	\$ 100.00	\$ 100.00
18	Rear Tailgate Lock Cover X NN	1	\$ 40.00	\$ 40.00
19	Rear Tailgate Lock Latch X NN	1	\$ 40.00	\$ 40.00
20	Rear Tailgate Inner Trim X NN	1	\$ 300.00	\$ 300.00
21	Rear Tailgate Inner Trim RH Cover X NN	1	\$ 60.00	\$ 60.00
22	Rear Tailgate Inner Trim Bottom Cover X NN	1	\$ 30.00	\$ 30.00
23	Rear Tailgate Inner Trim LH Cover X NN	1	\$ 60.00	\$ 60.00
24	Rear / End Panel Side Garnish X NN	1	\$ 80.00	\$ 80.00
25	Rear / End Panel Garnish Cover ? X NN	1	\$ 150.00	\$ 150.00
26	End Panel ? X R	1	\$ 450.00	\$ 450.00
Total Spare Parts				\$ 4,570.00

2218
 - 20%
 1774.40

ARC

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2202-078-TG

DATE : 9-Feb-2022

POLICY NO. : P10410802R01

VEHICLE REG. NO. : SLQ7063R

VEHICLE MAKE : HONDA FREED HYBRID 1.5G 2017

FOR SURVEYOR

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPECIAL NETT			
27	Rear Windscreen Sealant / <i>nec</i>	1	\$ 40.00	\$ 40.00
28	Supply and Installation of Solar film X <i>no</i>	1	\$ 280.00	\$ 280.00
29	Reverse Sensor / <i>hold</i>	21	\$ 200.00	\$ 200 400.00
Total Special Nett				\$ 720.00
	LABOUR			
30	Spray painting Rear Bumper, Tailgate, Fenders & Inner Panels	1	\$ 1,000.00	\$ 1,000.00
31	Remove, Replace, Repair and Refit Affected Area	1	\$ 1,200.00	\$ 1,200.00
32	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 100.00	\$ 100.00
33	Remove and Refit Rear Windscreen	1	\$ 150.00	\$ 150.00
34	Remove and Refit Rear Reverse Sensor	2	\$ 80.00	\$ 160.00
35	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
36	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,740.00
Amount Before Excess				\$ 8,030.00
Add GST @ 7%				562.10
Total Amount Payable				\$ 8,592.10

Estimate prepared by: RAZALI

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

Steve (LKK)

10/2/22 2.00pm

m R = 4734.40
L/S L/S-3787.52
ALY = 3800
4 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Repairer