



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



CHINA TAIPING INSURANCE P/L		NAME :		WIP : 17750			
3 ANSON ROAD		ADDRESS :		EXCESS :			
#16-00 SPRINGLEAF TOWER		TEL :		DATE: 10-Feb-22			
SINGAPORE 079909							
ATTN. : MOTOR CLAIMS							
FAX :							
VEH NO :	SME3700M	DATE IN :		CONTACT PERSON :	RONALD		
CHASSIS NO :	JM6GL1072K0303996	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM		
MODEL :	MAZDA 6	DATE REG.:	27-Sep-18	POLICY NO. :			
NATURE OF WORKS							
Parts Description							
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	FRONT FENDER LH	1			MGHP9-52-211A	bt✓	\$ 383.70
2	STAY FENDER LH	1			MGHP9-52-240D	re✓	\$ 48.30
3	MUD GUARD LH FRT	1			MGRF2-56-140	X nm	\$ 114.30
4	FASTENER	10			MB45A-56-146A	X nm	\$ 30.00
5	DOOR FRONT LH	1			MGHY0-59-02XJ	bt✓	\$ 975.20
6	STRIPE NO.3(L), BODY SIDE GL <i>sticker</i>	1			MGR6-50-8W3A00	re✓	\$ 12.90
7	STRIPE NO.1(L), BODY SIDE GL	1			MGR6-50-8W1A00	re✓	\$ 11.00
8	UPPER HINGE LH FRONT DOOR	1			MKD53-59-210A	X nm	\$ 44.10
9	LOWER HINGE LH FRONT DOOR	1			MD461-58-210B	X nm	\$ 41.70
10	WEATHERSTRIP LH FRT DOOR	1			MGBFN-59-760	X nm	\$ 90.70
11	FASTENER(L)	10			MTK48-59-762	re✓	\$ 92.00
12	PAD COVER FRONT DOOR	1			MGHP9-58-972	X nm	\$ 5.20
13	GROMMET,SCREW	12			MGJ6A-58-975	re✓	\$ 36.00
14	GROMMET,SCREW	1			M9991-00-503	re✓	\$ 3.80
15	FASTENER	5			MGJ6A-68-AB1	re✓	\$ 36.00
16	GARNISH LH FRONT DOOR	1			MGBFT-50-M20	re✓	\$ 99.10
17	CLIP,GARNISH	3			MKD53-50-M38	re✓	\$ 36.90
18	GARNISH(L),SAIL-OUT GJ/GL	1			MGJR9-69-16YB	re✓	\$ 96.60
19	CLIP,GARNISH	3			MGHP9-50-M38	re✓	\$ 33.00
20	MOULD OUTER FRONT DOOR LH	1			MGHP9-50-650F	X nm	\$ 96.00
21	STONE GUARD LH	1			MGHK1-50-490	re✓	\$ 198.00
22	CLIP	13			MBP4L-51-SJ3	re✓	\$ 130.00
23	CLIP	2			MG18K-51-SJ3	re✓	\$ 13.00
24	HARNES,FRONT DOOR LH	1			MGBKT-67-200	X nm	\$ 250.70
25	INSULATOR FENDER FRT LH	1			MGHP9-56-396A	X nm	\$ 81.30
26	PLATE SEAL FENDER FRT LH	1			MGHP9-56-J13	X nm	\$ 55.20
27	WHEEL,DISC 17"X7	1			M9965-16-7570	nm X	\$ 1,196.80
28	FRONT ABSROBER LH	1			MGBJD-34-900A	X	\$ 392.40
29	BEARING TOP FRT ABSROBER	1			MB45A-34-38XA	X	\$ 55.80
30	RUBBER MOUNTING TOP FRT ABSROBER	1			MKD35-34-380C	X	\$ 96.50
31	FRONT LOWER ARM LH	1			MG46C-34-350J	X	\$ 503.90
32	KNUCKLE LH FRT	1			MGBFN-33-031	X	\$ 420.00
33	HUB WHEEL BEARING FRT LH	1			MKD35-33-04XF	X	\$ 566.70
34	NUT	1			MD651-33-042A	X	\$ 15.00
35	0	0			0		\$ -

2205.50

2		TO RESPRAY FRONT FENDER LH , FRONT DOOR LH , ROCKER PANEL LH AND ALL AREAS AFFECTED BY THE ACCIDENTS.	2520 ✓	\$ 2,520.00
3	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	180 ✓	\$ 660.00
4	MZ-BR-AXNSUP	TO REPLACE AXLE AND SUSPENSION MECHANISM.	m X	\$ 660.00
5	MZ-BR-WHEAL	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	✓ NETT	\$ 560.00
6	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	m X NETT	\$ 120.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120 ✓	\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 300.00
9	MZ-BR-SUNDRI	SUNDRIES.	20	\$ 50.00

5560

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TOTAL LABOUR	\$ -	\$ 7,760.00
TOTAL PARTS	\$ -	\$ 6,261.80
TOTAL	\$ -	\$ 14,021.80
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ 14,021.80
GST 7%	\$ -	\$ 981.53
GRAND TOTAL	\$ -	\$ 15,003.33

SUPPLEMENTARY LABOUR DESCRIPTION

		REVISED	PRICES
1	#N/A		

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TOTAL LABOUR	\$ -	\$ -
TOTAL PARTS	\$ -	\$ -
TOTAL	\$ -	\$ -
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

Tanfikh 97495749 / 62563561
 WP 16/2/22 @ 11am
 6 days

Resurvey before paint
 tanfikh@lkhauto.com

TRANS EUROKARS PTE LTD

Authorised Signature

2205.50
 5560
 7765.50 #
 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: