

JEW MOTOR PTE LTD

ADDRESS: 60 JALAN LAM HUAT, #03-72
CARROS CENTER, SINGAPORE 737869

VEHICLE NUMBER: SKK3373R
MAKE AND MODEL: Nissan Qashqai
CHASSIS NUMBER:

NO.	PARTS	QTY	LIST PRICE	
1	TAILGATE	1	\$ 2,936.00	DT
2	TAILGATE LOGO	1	\$ 60.00	nc
3	TAILGATE "QASHQAI" EMBLEM	1	\$ 87.00	nc
4	TAILGATE PULL HANDLE	1	\$ 26.00	X SUC
5	TAILGATE INNER TRIM BOARD	1	\$ 317.00	nc
6	TAILGATE LOCK	1	\$ 117.00	X SUC
7	TAILGATE LOCK CATCH	1	\$ 32.00	X SUC
8	TAILGATE RH LAMP	1	\$ 216.00	nc
9	TAILGATE LH LAMP	1	\$ 216.00	nc
10	TAILGATE WEATHERSTRIP	1	\$ 159.00	nc
11	TAILGATE WINDSCREEN GLASS RUBBER MOULDING	1	\$ 118.00	nc
12	REAR BUMPER	1	\$ 755.00	DT
13	REAR BUMPER CLIPS	1SET	\$ 70.00	nc
14	REAR BUMPER RH REFLECTOR	1	\$ 55.00	nc
15	REAR BUMPER LH REFLECTOR	1	\$ 55.00	nc
16	REAR BUMPER REINFORCEMENT	1	\$ 620.00	nc
17	REAR BUMPER REINFORCEMENT RH BRACKET	1	\$ 126.00	X SUC
18	REAR BUMPER REINFORCEMENT LH BRACKET	1	\$ 126.00	X SUC
19	REAR BUMPER RH SIDE RETAINER	1	\$ 36.00	nc
20	REAR BUMPER LH SIDE RETAINER	1	\$ 36.00	nc
21	REAR BUMPER SPONGE	1	\$ 127.00	nc
22	REAR BUMPER TOWING COVER	1	\$ 28.00	nc
23	END PANEL	1	\$ 483.00	nc
24	END PANEL INNER GARNISH	1	\$ 65.00	nc
25	END PANEL ANTENNA SENSOR	1	\$ 76.00	X SUC
26	REAR RH FENDER INNER TRIM BOARD	1	\$ 366.00	X SUC
27	REAR LH FENDER INNER TRIM BOARD	1	\$ 366.00	X SUC
28	REAR FLOOR PANEL RH SIDE TRAY GARNISH	1	\$ 234.00	X SUC
29	REAR FLOOR PANEL LH SIDE TRAY GARNISH	1	\$ 234.00	X SUC
30	REAR FLOOR PANEL RH SPONGE TRAY	1	\$ 85.00	X SUC
31	REAR FLOOR PANEL LH SPONGE TRAY	1	\$ 85.00	X SUC
32	REAR FLOOR PANEL TOP COVER	1	\$ 395.00	X SUC
33	EXHAUST SILENCER HEAT SHIELD	1	\$ 138.00	X SUC
34	EXHAUST SILENCER	1	\$ 823.00	X SUC
35	EXHAUST SILENCER GASKET	1	\$ 45.00	X SUC

			\$ 9,713.00
		LESS 10%	\$ 971.30
		TOTAL	\$ 8,741.70

NO.	PARTS	QTY	SPECIAL NETT
1	REAR NUMBER PLATE	1	\$ 70.00
2	END PANEL SEALANT	1	\$ nec 50.00
2	REAR REVERSE SENSORS	1SET	\$ 300.00

KSIC
20
200
cut

	LABOUR AND MISC		
1	PANEL BEATING, REPLACE PARTS AND ALL AFFECTED AREAS	\$ 1,000.00	
2	SPRAY PAINTING ON ALL AFFECTED PARTS AND AREAS	\$ 1,200.00	
3	CHECK WIRING AND LIGHTING SYSTEM	\$ 100.00	
4	APPLY RUST COATING ON AFFECTED AREAS	\$ 100.00	
5	REMOVE AND REFIT TAILGATE WINDSCREEN GLASS	\$ 250.00	
6	REMOVE AND REPLACE TAILGATE INNER PARTS TO NEW TAILGATE	\$ 220.00	
7	REMOVE AND REPLACE REAR REVERSE SENSORS	\$ 100.00	
8	REMOVE AND REPLACE REAR GARNISH AND BOARDS	\$ 350.00	
9	REMOVE AND REPLACE EXHAUST SILENECER	\$ 220.00	

400 600
400 600
30
30
4,120
7.60
20
7.60
1.100

FINAL AMOUNT \$ 12,701.70

Thuan @Lkhauto.com
82235769
11/2/22 1700
S * 4 days wp
LIS
F: 6050
RD: S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: