

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT122001276/U943

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 24/2/22

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + RS, SI

) Photos

) Others

TOTAL

23/2/22 4/5 @ 4300 informed Ken (Cash \$5784.13, 57%)

24/02/22 @ 10-47am revised to Cecilia Lee by email.



SHIN AUTOMOBILE & TRADING PTE LTD

GST REGISTRATION: 201332279W

15 Kaki Bukit Road 4, #01-46, Bartley Biz Centre, S417808.

Office (65) 6385 5922
Fax (65) 6385 5921

Accident Repair Estimate

Vehicle No: SLV1596H

Make & Model: Honda Shuttle Hybrid 1.5

Date of Accident: 29/01/2022

not Authorized
WP
15/2/22
movable 90096608
L/S # 43001
5 days.
take photo after repair

S/N	Qty	Description	(S\$)
Parts			
1	1pcs	Rear Bumper 20/22 953	\$ 1,150.60
2	2pcs	Rear Bumper Side Retainer @28.4/pcs net	\$ 56.80
3	1pcs	Rear Bumper Sponge @56.5/pcs NF	\$ 113.00
4	3pcs	Rear Bumper Reflector @45.2/pcs 11	\$ 90.40
5	1pcs	Rear Bumper Reflector Garnish 45.8/pcs 11	\$ 91.60
6	2pcs	Rear Bumper Tow Cover 11	\$ 26.50
7	1pcs	Tail Gate 30/500	\$ 1,193.20
8	1pcs	Tail Gate Weatherstripe TW1	\$ 168.40
9	1pcs	Tail Gate Lock 3up	\$ 96.90
10	1pcs	Tail Gate Outer Garnish 11	\$ 168.40
11	1pcs	Tail Gate Emblem "Logo" 11	\$ 80.70
12	1pcs	Tail Gate Emblem "Shuttle" net	\$ 55.40
13	1pcs	Tail Gate Inner Trim Board 1001	\$ 320.40
14	1pcs	Tail Gate Reflector @340.8/pcs 822	\$ 681.60
15	1pcs	Tail Gate Pull Pocket 11	\$ 65.60
16	1pcs	Rear Windscreen Glass Moulding net	\$ 149.20
17	1pcs	Tail Lamp @520.5/pcs 11	\$ 1,041.00
18	1pcs	Rear End Panel 100	\$ 560.80
19	2pcs	Rear End Side Panel @108.8/pcs net	\$ 217.60
20	1pcs	Rear End Panel Inner Trim 11	\$ 287.60

202 Total \$ 6,615.70
(-)10% \$ 661.57
Parts Sub Total \$ 5,954.13

S/N	Qty	Special Nett	(S\$)
21	1set	Reverse Sensor should	\$ 250.00
22	1set	Rear Bumper Clips net	\$ 80.00
23	1set	Tail Gate Inner Trim Board Clips 11	\$ 80.00
24	1set	Rear Windscreen Clips 11	\$ 80.00
25	1set	Tail Gate Outer Garnish Clips 11	\$ 80.00
26	1set	Rear End Panel Inner Trim Clips 11	\$ 80.00
27	1set	Rear Windscreen Glass Inner Seal net	\$ 80.00
28	1set	Rear Windscreen Glass Sealant net	\$ 60.00
29	1set	Tailgate Sealant 11	\$ 80.00
30	1set	Rear End Panel Sealant net	\$ 80.00

Total \$ 950.00

S/N	Labour	(S\$)	
1	To check wiring sytsem.	\$ 80.00	20
2	To reset and reprogramme after repair.	\$ 200.00	50
3	To remove & refix interior upholstery	\$ 200.00	80
4	To remove & refix rear windscreen glass & rear RH fender glass	\$ 150.00	120
5	To remove & refix reverse sensor	\$ 100.00	50
6	To remove & refix tail gate mechanism	\$ 100.00	60
7	To reset and reprogramme after repair.	<i>Repetd</i> \$ 200.00	X
8	To cut and weild on rear end panel. To panel beat and straighten on spare tyre panel, rear both fenders. To r&r rear bumper, tailgate, taillamps and others attachments.	\$ 1,000.00	800
9	To putty and respray on rear bumper, tailgate, rear both fenders, rear end panel, spare tyre panel and accident affected areas.	\$ 1,000.00	800
10	To tuff coat affected areas	\$ 150.00	60
Labour Total:		\$ 3,180.00	
Sub Total (labour and parts):		\$ 10,084.13	

Vehicle is at 15 Kaki Bukit Road #01-46 Bartley Biz Centre Singapore 417808
Please arrange your surveyor to come down to survey the vehicle.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-3771.7
202
P-3017.36
S.N- 380
L- 2040
8437.36
202
4349