



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL	INV No.	AC2106809
64 CECIL STREET	INV Date	30/09/2021
#05-02 IOB BUILDING	Reference	CS3/GRB21010027/Evf3e2
SINGAPORE 049711	Code	GRB

PROFESSIONAL SERVICE FEE

Vehicle No.	FBK 1759G	Bill cancel refer to new invoice No. AC2200844 15/02/2022 \$261.00
Insured Veh.	SLT 641C	
Claim No.	MFL2021D0004118	
Policy No.	D21MFL0000447	
Accident Date	21/09/2021	
Inspection Date	28/09/2021	

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 28.09.2021 11.00am	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2200844

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 15/02/2022
Reference CS3/GRB21010027/Evf3e2-
'
Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. FBK 1759G
Insured Veh. SLT 641C
Claim No. MFL2021D0004118
Policy No. D21MFL0000447
Accident Date 21/09/2021
Inspection Date 28/09/2021

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	11.00
Note: Pls discard Inv.AC2106809 dated 30/09/2021 \$140.17	
Subtotal	261.00
GST (7%)	18.27
Grand Total	279.27

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM