

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001278/AVY3N2**Date:** 06/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00150742102
Claimant Vehicle No :	SFM9089X	Insured Vehicle No :	XE3095X
Date of Loss:	08/02/2022	Nature of Claim:	TP
		Claim No:	SNM22D200965/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFM9089X	Engine No:	27091030420262
Make & Model:	MERCEDES-BENZ CLA180, 1.6 (A)	Chassis No:	WDD1173422N101612
Reg. Date:	25/07/2014 (Man. Year: 2014)	Odometer:	95230 km
Colour:	Green		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,194.20	2,340.18	9,854.02	80.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	1,280.00	960.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,434.20	3,620.18	10,814.02	74.92
Approved Total (Overridden) (\$\$)		2,900.00		
Nett Amount (\$\$)	14,434.20	2,900.00	11,534.20	79.91

INSPECTION

Date of Assignment:	10/02/2022	
Date Inspected:	24/02/2022	Inspected At: Lc Automotive (Sin Ming) Blk 10 Sin Ming ind estate sector C #01-20 Singapore 575645
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2022)
Parts:	143	MERCEDES-BENZ CLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFM9089X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	1,445.00 F	*- FN
2	1		*REAR BUMPER SIDE BRACKET-RH	Not Necessary	45.00 F	*- FN
3	1		*REAR FENDER RH	Repair	1,954.00 F	*- FN
4	1		*REAR FENDER RH COWLING	Not Necessary	144.00 F	*- FN
5	1		*REAR R/H DOOR	Dented	1,950.20 F	*1,950.20 FN
6	1		*REAR R/H DOOR INNER LOCK	Not Necessary	590.00 F	*- FN
7	1		*REAR R/H DOOR TOP MOULDING	Not Necessary	117.00 F	*- FN
8	2		*REAR R/H DOOR TOP LOWER HINGE	Not Necessary	224.00 F	*- FN
9	1		*REAR R/H DOOR GEAR MOTOR ASSY	Damaged	855.00 F	*525.00 FN
10	1		*REAR R/H DOOR OUTER HANDLE	Not Necessary	215.00 F	*- FN
11	1		*REAR R/H DOOR INNER TRIM BOARD	Not Necessary	1,480.00 F	*- FN
12	1		*REAR R/H DOOR INNER RUBBER	Necessary	125.00 F	*125.00 FN
13	1		*FRONT DOOR-RH	Repair	1,950.00 F	*- FN
14	1		*REAR RIM-RH	Not Necessary	800.00 F	*- FN
15	1		*REAR TYRE-RH	Not Necessary	300.00 F	*- FN
					Sub Total (\$\$)	12,194.20 2,600.20
					- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00 260.02
					Total Parts (\$\$)	12,194.20 2,340.18

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX CUSHION	New	120.00	100.00
2	TUFF KOTE	New	120.00	30.00
3	SPRAY PAINTING	New	1,000.00	750.00
4	PANEL BEATING	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,240.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >