

LC AUTOMOTIVE

25 KAKI BUKIT ROAD 4 #05-26 Synergy @ KB Singapore 417800

NG KIM HUAT
25 KAKI BUKIT ROAD4
03-65 SYNERGY @KB
Singapore 417800

22ND FEB 2022

TP Chinn
VERON.

Accident date: 08th FEB 2022

Estimated repair cost for vehicle no: SFM9089X Mercedes CLA 180 '2014 JULY'

S/n	Qty	Items/Nett	U/price	Amount
1	1	Rear bumper		\$1,445.00
2	1	Rear bumper side bracket-RH		\$45.00
3	1	Rear fender RH		\$1,954.00
4	1	Rear fender R/H cowling		\$144.00
5	1	Rear R/H door		\$1,950.20
6	1	Rear R/H door inner lock		\$590.00
7	1	Rear R/H door top moulding		\$117.00
8	2	Rear R/H door top lower hinge	\$112.00	\$224.00
9	1	Rear RH door gear motor assy		\$855.00
10	1	Rear R/H door outer handle		\$215.00
11	1	Rear R/H door inner trim board		\$1,480.00
12	1	Rear R/H door inner rubber		\$125.00
13	1	Front door -RH		\$1,950.00
14	1	Rear rim -RH		\$800.00
15	1	rear tyre -RH		\$300.00

Labour charges

2600.20

Subtotal :- \$12,194.20

To Remove & refix cushion

2340.18

\$120.00

tuff Kote

1280

\$120.00

Spray painting

\$1,000.00

Panel beating

\$1,000.00

Subtotal :- \$2,240.00

Total:- \$14,434.20

total: 3620.18

L/S: 2.9K

0.3Days

2.9K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: