

1 of 2 ?

100%

Find | Next

LKK

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

(SINGAPORE BRANCH)

60 ANSON ROAD #08-01 (8th FLOOR)

MAPLETREE ANSON

SINGAPORE 079914

Ref: CS3/AWA22001279/Vvf3

Date: 10/02/2022

Code: AWA

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YN 9305S	Veh. Inspected	SLX 4330C
Policy No.	BVFCB0013842100	Coverage (\$)	0.00
Claim No.	NSV2200019/HLF	Excess (\$)	0.00
Assign From	HEW LEE FONG	Assign Date	10/02/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/02/2022	Inspection Date	11/02/2022
Survey held at	SPEEDWERKZ PTE LTD 13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

https://views.init.com.sg/report/reportserver?Report=LKKInspection&From=344956&rs:Command=Render&rc:Parameters=false&rc:Zoom=Page ...

1/1