

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD #09-01

SINGAPORE 068897

TEL: 6714 3369

ATTN: Motor Claim Department

Claim Type: Third Party

Accident Date: 08/02/2022

TP Veh Reg No: SNA7702R

Estimate No: EST2200040

Date: 09 Feb 2022

Veh Reg No: **SJN4791G**

Make/Model: HONDA JAZZ 1.3L AT

Chasis No: JHMGE68509S215951

Reg. Date: 17/02/2009

Your Ref No: SNA7702R

Estimate Repair Cost to Vehicle No :SJN4791G

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BOOT LID	844.10	
2	2 PCS BOOTLID HINGE	124.40	
3	1 PC BOOT LID LOGO	50.20	
4	1 PC BOOT LID "JAZZ" EMBLEM	48.80	
5	1 PC REAR WINDSCREEN GLASS	890.90	
6	1 PC REAR WINDSCREEN RUBBER	120.50	
7	1 PC REAR WIPER MOTOR	268.00	
8	1 PC REAR WIPER BLADE	45.00	
9	1 PC REAR WIPER ARM	68.40	
10	1 PC THIRD BRAKE LIGHT	288.40	
11	2 PCS REAR NUMBER PLATE LAMP	125.80	
12	1 PC BOOT LID OUTER OPENER HANDLE	98.60	
13	1 PC BOOT LID INNER LOCK	189.50	
14	1 PC BOOT LID INNER LOCK CHECKER	38.90	
15	1 PC BOOT LID RUBBER	182.40	
16	1 PC BOOTLID TRIM	177.20	
17	1 PC REAR BOOT COMPARTMENT COVER	367.10	
18	1 PC BOOT LID OUTER GARNISH	166.90	
19	1 PC REAR PANEL	496.50	
20	1 PC REAR PANEL TRIM	90.80	
21	1 PC SPARE TYRE PANEL	737.00	
22	1 PC SPARE TYRE COVER	289.60	
23	1 PC SPARE TYRE TOOL SPONGE	236.80	
24	1 PC REAR FENDER LH	786.90	
25	1 PC REAR FENDER TRIM LH	286.50	
26	1 PC REAR FENDER INNER TOP TRIM LH	166.90	
27	1 PC REAR FENDER QUARTER GLASS LH	298.60	
28	1 PC REAR FENDER MUDFLAP LH	58.80	
29	1 PC TAIL LAMP LH	366.40	
30	1 PC TAIL LAMP PANEL LH	189.60	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD #09-01

SINGAPORE 068897

TEL: 6714 3369

ATTN: Motor Claim Department

Claim Type: Third Party

Accident Date: 08/02/2022

TP Veh Reg No: SNA7702R

Estimate No: EST2200040

Date: 09 Feb 2022

Veh Reg No: SJN4791G

Make/Model: HONDA JAZZ 1.3L AT

Chasis No: JHMGE68509S215951

Reg. Date: 17/02/2009

Your Ref No: SNA7702R

Estimate Repair Cost to Vehicle No :SJN4791G

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
31	1 PC TAIL LAMP - RH	366.40	
32	1 PC TAIL LAMP PANEL RH	189.60	
33	1 PC TAIL LAMP LH INNER COVER	77.60	
34	1 PC REAR BUMPER	497.70	
35	2 PCS REAR BUMPER SIDE RETAINER	79.60	
36	1 PC REAR TOWING COVER	23.60	
37	1 PC EXHAUST PIPE	689.50	
38	2 PCS EXHAUST PIPE MOUNTING	65.60	
		10,089.10	
	Less 20%	2,017.82	8,071.28
	Special Net		
39	1 PC REAR WINDSCREEN SEAL	60.00	
40	1 PC REAR WINDSCREEN SEALANT	60.00	
41	1 PC REAR NUMBER PLATE	50.00	
42	1 SET BOOTLID TRIM CLIPS	60.00	
43	1 SET REAR PANEL TRIM CLIPS	40.00	
44	1 SET REAR FENDER TRIM CLIPS LH	60.00	
45	1 SET REAR LH FENDER INNER TOP TRIM CLIPS	60.00	
46	1 PC REAR FENDER QUARTER GLASS LH SEAL	60.00	
47	1 PC REAR FENDER QUARTER GLASS LH SEALANT	60.00	
48	1 SET REAR FENDER MUDFLAP CLIPS LH	30.00	
49	1 SET REAR BUMPER CLIPS	40.00	
50	1 SET REVERSE SENSORS	250.00	
51	1 PC REAR WINDSCREEN GLASS SOLAR FILM	280.00	
		1,110.00	1,110.00
	Labour		
52	1 TO CHECK WIRING	50.00	
53	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
54	1 TO REMOVE AND REFIT THIRD BRAKE LIGHT	80.00	
55	1 TO REMOVE AND REFIT SEAT CUSHION	280.00	
56	1 TO REMOVE AND REFIT LH FENDER QUARTER GLASS	120.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD #09-01

SINGAPORE 068897

TEL: 6714 3369

ATTN: Motor Claim Department

Claim Type: Third Party

Accident Date: 08/02/2022

TP Veh Reg No: SNA7702R

Estimate No: EST2200040

Date: 09 Feb 2022

Veh Reg No: **SJN4791G**

Make/Model: HONDA JAZZ 1.3L AT

Chasis No: JHMGE68509S215951

Reg. Date: 17/02/2009

Your Ref No: SNA7702R

Estimate Repair Cost to Vehicle No :SJN4791G

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
57	1 SET REVERSE SENSORS	80.00	
58	1 TO REMOVE AND REFIT PETROL TANK	150.00	
59	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	150.00	
60	1 TO SPRAY UNDERSEAL	200.00	
61	1 (REAR) TO SPRAY PAINTING	1,700.00	
62	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,800.00	
		4,730.00	4,730.00
		Total	S\$ 13,911.28
		Add GST @ 7%	973.79
		Total Amount Payable	<u>S\$ 14,885.07</u>

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND EIGHT HUNDRED EIGHTY FIVE AND CENTS SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE