

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01
SINGAPORE 068897
TEL: 6714 3369
ATTN: Motor Claim Department

Estimate No: EST2200040
Date: 09 Feb 2022
Veh Reg No: SJN4791G
Make/Model: HONDA JAZZ 1.3L AT
Chasis No: JHMGE68509S215951
Reg. Date: 17/02/2009
Your Ref No: SNA7702R

Claim Type: Third Party
Accident Date: 08/02/2022
TP Veh Reg No: SNA7702R

Estimate Repair Cost to Vehicle No :SJN4791G

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID Distorted	844.10	✓
2	2 PCS BOOTLID HINGE <i>new</i>	124.40	+
3	1 PC BOOT LID LOGO <i>new</i>	50.20	✓
4	1 PC BOOT LID "JAZZ" EMBLEM <i>new</i>	48.80	✓
5	1 PC REAR WINDSCREEN GLASS Shattered	890.90	✓
6	1 PC REAR WINDSCREEN RUBBER <i>new</i>	120.50	✓
7	1 PC REAR WIPER MOTOR <i>Damage</i>	268.00	✓
8	1 PC REAR WIPER BLADE <i>new</i>	45.00	+
9	1 PC REAR WIPER ARM <i>new</i>	68.40	✓
10	1 PC THIRD BRAKE LIGHT <i>new</i>	288.40	+
11	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	125.80	+
12	1 PC BOOT LID OUTER OPENER HANDLE <i>new</i>	98.60	+
13	1 PC BOOT LID INNER LOCK <i>Damage</i>	189.50	✓
14	1 PC BOOT LID INNER LOCK CHECKER <i>new</i>	38.90	+
15	1 PC BOOT LID RUBBER <i>cut</i>	182.40	✓
16	1 PC BOOTLID TRIM <i>cracked</i>	177.20	✓
17	1 PC REAR BOOT COMPARTMENT COVER <i>Delnd</i>	367.10	✓
18	1 PC BOOT LID OUTER GARNISH <i>Delnd</i>	166.90	✓
19	1 PC REAR PANEL <i>Distorted</i>	496.50	✓
20	1 PC REAR PANEL TRIM <i>Delnd</i>	90.80	✓
21	1 PC SPARE TYRE PANEL <i>Rejs</i>	737.00	+
22	1 PC SPARE TYRE COVER <i>Delnd</i>	289.60	✓
23	1 PC SPARE TYRE TOOL SPONGE <i>Delnd</i>	236.80	✓
24	1 PC REAR FENDER LH <i>Buckled</i>	786.90	✓
25	2 PC REAR FENDER TRIM <i>Delnd</i>	573	✓
26	1 PC REAR FENDER INNER TOP TRIM LH <i>new</i>	166.90	+
27	1 PC REAR FENDER QUARTER GLASS LH <i>new</i>	298.60	+
28	1 PC REAR FENDER MUDFLAP LH <i>new</i>	58.80	+
29	1 PC TAIL LAMP LH <i>cracked</i>	366.40	✓
30	1 PC TAIL LAMP PANEL LH <i>Distorted</i>	189.60	✓

8386

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01
SINGAPORE 068897
TEL: 6714 3369
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 08/02/2022
TP Veh Reg No: SNA7702R

Estimate No: EST2200040
Date: 09 Feb 2022
Veh Reg No: SJN4791G
Make/Model: HONDA JAZZ 1.3L AT
Chasis No: JHMGE68509S215951
Reg. Date: 17/02/2009
Your Ref No: SNA7702R

Estimate Repair Cost to Vehicle No :SJN4791G

Quantity	Description	List Price	Amount
		SS	SS
31	1 PC TAIL LAMP - RH <i>Excluded</i>	366.40	285
32	1 PC TAIL LAMP PANEL RH <i>Peris</i>	189.60	+
33	1 PC TAIL LAMP LH INNER COVER <i>Del'd</i>	77.60	✓
34	1 PC REAR BUMPER <i>Dist'd</i>	497.70	✓
35	2 PCS REAR BUMPER SIDE RETAINER <i>neu</i>	79.60	✓
36	1 PC REAR TOWING COVER <i>neu</i>	23.60	+
37	1 PC EXHAUST PIPE <i>3 neu</i>	689.50	+
38	2 PCS EXHAUST PIPE MOUNTING	65.60	+
		10,089.10	10,375.60
	Less 20%	2,017.82	8,071.28
	Special Net		
39	1 PC REAR WINDSCREEN SEAL <i>3 neu</i>	60.00	40
40	1 PC REAR WINDSCREEN SEALANT	60.00	40
41	1 PC REAR NUMBER PLATE <i>Best</i>	50.00	✓
42	1 SET BOOTLID TRIM CLIPS <i>neu</i>	60.00	30
43	1 SET REAR PANEL TRIM CLIPS <i>neu</i>	40.00	20
44	1 SET REAR FENDER TRIM CLIPS LH <i>neu</i>	60.00	30
45	1 SET REAR LH FENDER INNER TOP TRIM CLIPS <i>neu</i>	60.00	+
46	1 PC REAR FENDER QUARTER GLASS LH SEAL <i>neu</i>	60.00	20
47	1 PC REAR FENDER QUARTER GLASS LH SEALANT <i>neu</i>	60.00	20
48	1 SET REAR FENDER MUDFLAP CLIPS LH <i>neu</i>	30.00	+
49	1 SET REAR BUMPER CLIPS <i>neu</i>	40.00	✓
50	1 SET REVERSE SENSORS <i>Dangd</i>	250.00	200
51	1 PC REAR WINDSCREEN GLASS SOLAR FILM <i>neu</i>	280.00	200
52	1 PC REVERSE CAMERA <i>Dangd</i>	480.00	380
		1,590.00	1,590.00
	Labour		
53	1 TO CHECK WIRING	50.00	30
54	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	✓
55	1 TO REMOVE AND REFIT THIRD BRAKE LIGHT	80.00	+
56	1 TO REMOVE AND REFIT SEAT CUSHION	280.00	80

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01
SINGAPORE 068897
TEL: 6714 3369
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 08/02/2022
TP Veh Reg No: SNA7702R

Estimate No: EST2200040
Date: 09 Feb 2022
Veh Reg No: SJN4791G
Make/Model: HONDA JAZZ 1.3L AT
Chasis No: JHMGE68509S215951
Reg. Date: 17/02/2009
Your Ref No: SNA7702R

Estimate Repair Cost to Vehicle No :SJN4791G

Quantity	Description	List Price	Amount
		SS	SS
57	1 TO REMOVE AND REFIT LH FENDER QUARTER GLASS	120.00 60	
58	1 SET REVERSE SENSORS	80.00 50	
59	1 TO REMOVE AND REFIT PETROL TANK	150.00 80	
60	1 TO REMOVE AND REFIX REAR EXHAUST PIPE 3510	150.00 X	
61	1 TO SPRAY UNDERSEAL	200.00 100	
62	1 (REAR) TO SPRAY PAINTING	1,700.00 1400	
63	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,800.00 1400	
64	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00 50	
	To transfer tailgate fittings. 150 80	4,810.00	4,810.00
	To vacuum and clean up glass shards. 120 60	Total	S\$ 14,471.28
	Add GST @ 7%		1,012.99
	Total Amount Payable		S\$ 15,484.27

14,970.48

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND FOUR HUNDRED EIGHTY FOUR AND CENTS TWENTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adrian Lij
L/S 11/02/22

10 Days

total: 10389.68
L/S: 8.3K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8.3K