## **FINAL COST OF REPAIR**

(To be completed for only one type of item)

То:				From:				Ref	BB75/(9AMB)/92FMD/22/03		
KRANJI CMTL Unit					9AMB/92FMD/MOS Base/LEO Area Office						
Description of Item: TGM 18.280 4X4 SOFT RF W				N/CONT	/CONT FR A1C/A1E			SAF <sup>2</sup>	1222:		
Part/Reg No: MID21976 Orginal Value:		al Value:	\$204,053			Da	Date:		1		
	01 CE/Non CE:			Non CE			SAF	1204/SAF	1351:		
Description on Costs of Repairs:			1401				Wor	Date: Workshop Job N		8202711139	
besonption on oosts of Kep	an s.								Date:	110.	26.01.2022
MATERIAL COST											
DESCRIPTION MIRROR HEAD,VEH:WIDE VIE	W MIRROR				Oty	1		Unit Price 117.58			Total Price \$117.58 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00
LABOUR COST										Rate	\$28.00
REMOVE AND REPLACE SIDE MIRROR					1	\$	28.00			\$28.00 \$0.00	
A											\$0.00 \$0.00
Assessment Fee											
In-inspection and Quality Check						1	\$	28.00			\$28.00
General Services											
Tow Svc Wheeled (< 3 Ton)											\$0.00
Base/LEO Area Office's Asses	sment of D	amages									
Labour Ch	narges @	\$28.00	per hour x per hour x		1			hrs =	\$28	3.00	
Sub-contr Assessme Towing Se 7% GST Grand Tot	ent Fee rvice al							= = =	\$28 \$0	7.58 3.00 .00 <b>3.58</b>	
Estimated Time for Repair:	1										

\*Delete whichever is not applicable