

MBM WHEELPOWER PTE. LTD.



YOUR REF.:
OUR REF.: SMC6425Z

TO: CHINA TAIPING
CC: MOTOR CLAIMS DEPARTMENT

FAX:

Not Authorised
Refusing B4 paint
ex @ 1250k
4 days
89745.76

DATE: 28 January 2022
FROM: Alvin Koh
FAX: 64525333
CONTACT: 81387188
MAKE & MODEL: BMW 520i SE SALOON
CHASSIS NO.: WBAJA12010BJ20041
ENGINE NO.: 22365262B48B20A
YEAR MADE: 2018
ACCIDENT DATE: 24 January 2022

ESTIMATE FOR VEHICLE NO.: SMC6425Z

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	BONNET <i>(Aluminium)</i>	2920	1	\$ 3,421.00 ✓
2	BONNET HINGE LH		1	\$ 103.00 X
3	BONNET HINGE RH		1	\$ 103.00 X
4	BONNET DAMPER LH		1	\$ 181.00 X
5	BONNET DAMPER RH		1	\$ 181.00 ✓
6	BONNET WEATHER STRIP		1	\$ 260.00 X
7	BONNET LOCK		1	\$ 485.00 X
8	BONNET BMW EMBLEM		1	\$ 149.00 ✓
9	HEADLAMP RH		1	\$ 4,940.00 ✓
10	FRONT BUMPER		1	\$ 2,156.00 ✓
11	FRONT BUMPER TOWING COVER		1	\$ 153.00 X
12	FRONT BUMPER RETAINER RH		1	\$ 104.00 X
13	FRONT BUMPER GRILLE RH		1	\$ 264.00 X
14	FRONT BUMPER REINFORCEMENT		1	\$ 855.00 X
15	FRONT BUMPER SPONGE		1	\$ 173.00 X
16	FRONT AIR DUCT		1	\$ 641.00 X
17	FRONT BRAKE DUCT RH		1	\$ 124.00 X
TOTAL:				\$ 14,293.00
LESS 10%:				\$ (1,429.30)
PARTS TOTAL:				\$ 12,863.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SPECIAL NETT

BODY SEALANT
FRONT BUMPER CLIP
NUMBER PLATE & HOLDER
FRONT BUMPER COMPLETE

\$	<i>na</i>	80.00	X
\$	<i>nr</i>	100.00	X
\$	<i>su</i>	60.00	X
\$	<i>supervisor</i>	2,500.00	X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS
TO APPLY ANTI RUST COATING
TO REMOVE & REPLACE BUMPER SENSORS
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO SPRAY PAINT ON THE AFFECTED AREAS

	<i>400l</i>	
\$		800.00
\$	<i>n2</i>	80.00 X
\$	<i>60l</i>	120.00 X
\$	<i>130l</i>	250.00
\$	<i>20l</i>	50.00
\$	<i>500l</i>	800.00
TOTAL: \$		17,703.70
7% GST: \$		1,239.26
GRAND TOTAL: \$		18,942.96

C12/ 22 001284/K9

MBM WHEELPOWER PTE. LTD.



YOUR REF.:

OUR REF.: SMC6425Z

TO: CHINA TAIPING

CC: MOTOR CLAIMS DEPARTMENT

FAX:

DATE: 18 February 2022
FROM: Alvin Koh
FAX: 64525333
CONTACT: 81387188
MAKE & MODEL: BMW 520I SE SALOON
CHASSIS NO.: WBAJA12010BJ20041
ENGINE NO.: 22365262B48B20A
YEAR MADE: 2018
ACCIDENT DATE: 24 January 2022

SUPPLEMENTARY FOR VEHICLE NO.: SMC6425Z

NO.	DESCRIPTION
1	FRONT BUMPER FOG LAMP SUPPORT RH
2	FRONT AIR FLAP BOTTOM
3	FRONT BUMPER SPONGE BOTTOM
4	FRONT BUMPER LOWER REINFORCEMENT
5	FRONT BUMPER REINFORCEMENT ADJUSTABLE ELEMENT RH
6	FRONT ENGINE UNDER COVER

PART NO.

QTY.		LIST PRICE	
1	\$	CM	174.00.
1	N.C \$	CM X	425.00
1	N.C \$	CM X	157.00
1	N.C \$	Bu X	529.00
1	\$	Bu X	20.00
1	\$	Bu X	248.00

TOTAL:	\$	1,553.00
LESS 10%:	\$	(155.30)
PARTS TOTAL:	\$	1,397.70

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS

\$ N X 200.00

TOTAL:	\$	1,597.70
7% GST:	\$	111.84
GRAND TOTAL:	\$	1,709.54