

Toughie

OS	CT	2200	286	T	y3
----	----	------	-----	---	----

ASSIGNMENT

TOTAL



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE GST Registration No. 201118055N Company Registration No: 201118055N

ESTIMATE

Everest Leasing Pte Ltd
169 KAKI BUKIT AVENUE 1 #03-03 SHUN LI
INDUSTRIAL PARK Singapore 416019

Contact : 87771128-Evan

Code : C102031

Date in : 24/02/2022

Vehicle Num. : GBG9588B

Model : NISSAN NV350 PANEL VAN 2.5 5AT 5D
R EURO V

Chassis/Eng# : JN1MC2E26Z0009718/YD25003020B

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
Front bumper	1	576.90	576.90
Front bumper fog lamp cover LH	1	117.50	117.50
Front bumper fog lamp LH	1	311.80	311.80
Front bumper reinforcement	1	705.00	705.00
Front bumper side retainer LH	1	164.50	164.50
Front door hinges	2	60.90	121.80
Front door LH	1	1071.90	1,071.90
Front door rubber moulding	1	157.80	157.80
Front door step panel garnish LH	1	176.10	176.10
Front door step panel LH	1	57.90	57.90
Front headlamp LH	1	355.90	355.90
Percentage discount 10% (Nett Price)			
Front bumper clips (Set)(SN)	1	50.00	50.00
Front door company registration sticker (SN)	1	20.00	20.00



Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg ; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE GST Registration No. 201118055N Company Registration No: 201118055N

LABOUR

Description	Price
Diagnose, replace and/or repair to rectify front portion electrical system for proper functioning.	120.00 30
To remove, reinstall front door window glass. (to FR)	120.00 X
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800.00 400
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	900.00 400
To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.	200.00 30

page 2

Tanphie 97495949
'WP' 24/2/22 @ 335pm
L/S Resurvey after repair
Tanphie & Lkhanda.com
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: