

1

of 2 ?

<

>

<<

>>

↺

↻

100%

▼

📄

🖨

Find | Next

LKK

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

50 RAFFLES PLACE #03-03

SINGAPORE LAND TOWERSINGAPORE 048623

Ref: CS3/SMO21011127/Uvf3-1

Date: 10/02/2022

Code: SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJX 5990P	Veh. Inspected	SMW 4040H
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2103237/GPL	Excess (\$)	0.00
Assign From	GNOH PAU LOONG	Assign Date	10/02/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	29/10/2021	Inspection Date	10/02/2022
Survey held at	3 MOTORWERKZ 25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42 SINGAPORE 417800		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

https://views.init.com.sg/report/reportserver?Report=LKKInspection&From=344966&rs:Command=Render&rc:Parameters=false&rc:Zoom=Page ...

1/1