

TPAXA
Veron

CB7269A. 2013 Oct.
Nissan NV350 2488 cc
JN1TC2E26Z0000099.

Front Bumper Distorted	541.40 /
Front Bumper Clips. <i>new</i>	30(SN) /
Front Bumper Side Holder x 02 <i>LH Damaged</i>	111.50 $111.5 \times 2 = 223$
Front Bumper Fog Lamp LH. <i>Crushed</i>	295.40 /
Front Bumper Fog Lamp Garnish LH. <i>Damaged</i>	105.10. /
Front Bumper Reinforcement. <i>XLF New</i>	345.40 +
Front Grille <i>Crushed</i>	455.80 /
Front Grille Logo <i>new</i>	68.30 /
Front Grille Clips	20(SN) /
Headlamp LH. <i>Crushed</i>	477.50. /
Front LH Door <i>Repair</i>	1232.50 +
Front LH Door Pillar <i>Repair</i>	899.20 +
Front LH Step Garnish. <i>torn</i>	282.30 /
Front LH Step Garnish Clips. <i>new</i>	20(SN) /

CB7269A.

Front LH Wheel Arc Panel ^{Repr} 545.80 +
Front LH Wheel Arc Panel Top Garnish ^{Repr} 182.10 ✓
Front LH Wheel Arc Panel Top Garnish Clips ^{MC} 20(SN) ✓
2519.40 S.N: 90
2267.46

Panel Beating

Spray Painting

Wiring.

To remove upholstery.

To remove dashboard.

To transfer front door fittings.

To spray tuft coat

~~1500~~ 800.

1400 6000

~~50~~ 30

~~180~~ 60.

350 +

150 +

~~150~~ 60.

4498

9494.30

total: 39074.6

L/S: 3.1K.

05 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Stamp: