

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Email Address : xinhuaworkshop1@gmail.com

Reg : 201838521G

Vehicle Number : SMM4481X
Vehicle Model : RENAULT GRAND SCENIC
Accident Date : 01.02.2022
Original Reg Date : 28.06.2019

Date : 09.02.2022
Chassis : VF1RFA00X62673000
TP Ins. : AIG *Asher*

ESTIMATE

1	1	RR BUMPER	<i>torn</i>	\$ 1,345.00	✓
2	1	RR BUMPER LOW	<i>Repair</i>	\$ 645.30	X.
3	1	RR BUMPER LOW MLDG	<i>Not m</i>	\$ 812.00	X
4	1	RR BUMPER TOW COVER	<i>Not m</i>	\$ 104.00	X
5	1	RR BUMPER CENTRE RETAINER	<i>Not m</i>	\$ 417.00	X
6	1	RR BUMPER SIDE RETAINER LH(INNER)	<i>3 m</i>	\$ 171.00	95
7	1	RR BUMPER SIDE RETAINER LH(OUTER)	<i>3 m</i>	\$ 335.00	150
8	1	RR BUMPER LOW BRACKET LH	<i>3 m</i>	\$ 132.00	X
9	2	RR BUMPER LOW BRACKET CENTRE	<i>Not m</i>	\$ 202.00	X
10	1	RR FENDER INNERSHIELD END LH	<i>Not</i>	\$ 274.00	✓
11	1	RR BUMPER REINFORCEMENT		\$ 799.00	}
12	1	RR KEY RECEIVER SENSOR		\$ 297.00	
13	2	RR BUMPER REVERSE SENSOR		\$ 594.00	}
14	2	RR BUMPER REVERSE SENSOR HOLDER		\$ 165.80	
15	2	RR BUMPER BLIND SPOT SENSOR		\$ 968.00	}
16	6	RR BUMPER REVERSE SENSOR RUBBER SEAL		\$ 84.00	
17	1	RR BUMPER REVERSE SENSOR WIRE HARNESS		\$ 261.00	}
18	1	RR BUMPER REFLECTOR LH		\$ 516.00	
19	1	RR TAILGATE MLDG		\$ 552.00	}
20	1	RR TAILGATE		\$ 3,720.00	
21	1	RR TAILGATE RENAULT LOGO		\$ 193.00	}
22	1	RR TAILGATE SCENIC EMBLEM		\$ 176.00	
23	1	RR TAILGATE RENAULT EMBLEM		\$ 152.00	}
24	2	RR TAILGATE NUMBER PLATE LAMP	<i>Not</i>	\$ 80.00	
25	1	RR TAILGATE LOCK	<i>Not</i>	\$ 353.00	}
26	1	RR TAILGATE LOCK STRIKER	<i>Not</i>	\$ 114.00	
27	1	RR TAILGATE DAMPER		\$ 265.00	}
28	1	RR TAILGATE LOCK OPEN SWITCH		\$ 231.00	
29	1	RR TAILGATE STOPPED		\$ 628.00	}
30	1	RR TAILGATE INNER TRIM BOARD		\$ 950.00	
31	1	RR TAILGATE REFLECTOR LH		\$ 640.00	}
32	1	RR TAILGATE WHEATERSTRIP		\$ 230.00	
33	1	RR TAILLAMP LH		\$ 640.00	}
34	1	RR END PANEL OUTER		\$ 1,088.00	
35	1	RR END PANEL INNER		\$ 492.00	}
36	1	RR END PANEL SUPORT LH		\$ 359.00	
37	1	RR END PANEL TOP GARNISH		\$ 332.00	}

38	1	RR TAILLAMP PANEL LH		\$	419.00	x
39	1	RR FENDER INNERSHIELD LH		\$	391.00	x
40	1	RR FENDER AIR DUCT LH		\$	195.00	x
41	1	RR FENDER MUDGUARD LH(RR)		\$	135.00	x
42	1	RR FENDER INNER TRIM LH		\$	749.00	x
43	1	RR FENDER LH	Repairs	\$	1,254.90	x
44	1	RR DOOR LH	Buckles.	\$	1,548.60	✓
45	1	SIDESKIRT LH	Not Mv	\$	879.60	x
46	1	RR RIM LH	cut	\$	1,458.30	880(SN).
47	1	RR WHEEL HUB BEARING LH	Damaged	\$	549.30	✓
48	1	RR ABSORBER LH	Not Nec	\$	385.90	x.

\$ 27,282.70

Less 10% \$ 2,728.27

\$ 24,554.43

3961.90

3565.71 S/N: 880

Special Nett

1	10	RR BUMPER CLIP	Nec	\$	100.00	30
2	10	RR TAILGATE GARNISH CLIP		\$	50.00	x
3	1	RR NUMBER PLATE		\$	200.00	x
4	1 SET	RR FENDER INNER SHIELD CLIPS		\$	30.00	x
5	1	Body Panel Joint Sealer		\$	65.00	x.

Labour charge

To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$	1,800.00	400
Carry out spray painting on affected area	\$	1,800.00	800.
To conduct anti rust of under carriage tuff coat	\$	100.00	40
To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$	120.00	30
To remove and refix reverse sensor and conduct test	\$	120.00	50
To remove and refix reverse camera and conduct test	\$	120.00	x
To conduct transfer of parts from old tailgate to new tailgate	\$	180.00	x
To conduct water leakage test after repairs of vehicle	\$	80.00	x
To remove and refix rear undercarriage	\$	200.00	x.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total \$ 29,519.43

Total: 529571

h/s: 46K

4days

46K