

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Alfred Toh

Date: 13 Apr 2022

## **Preliminary Advice**

|               |                                                  |                  |              |
|---------------|--------------------------------------------------|------------------|--------------|
| Insured       | : SLS2990L                                       |                  |              |
| Vehicle No    |                                                  |                  |              |
| TP Vehicle    | : SMS2607H                                       | Accident Date    | : 08/02/2022 |
| No            |                                                  |                  |              |
| Make          | : MAZDA 6                                        | Assignment Date  | : 12/02/2022 |
| Date of       | : 15/02/2022                                     | Est. Duration of | : 6          |
| Inspection    |                                                  | Repair           |              |
| Inspection At | : BIFROST AUTO PTE LTD (KAKI BUKIT)              |                  |              |
|               | 8 KAKI BUKIT AVE 4, #01-49, PREMIER @ KAKI BUKIT |                  |              |
|               | SINGAPORE 415875                                 |                  |              |

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 13,419.23 |
| Revised Amount              | :S\$ | 6,277.52  |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 6,277.52  |

|                 |      |          |
|-----------------|------|----------|
| Lump Sum Repair | :S\$ | 5,000.00 |
|-----------------|------|----------|

## **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |

|                   |      |
|-------------------|------|
| Salvage Value     | :S\$ |
| Margin for Repair | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.