

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	📄 ▼	🖨	Find Next
---	---	----------	---	---	---	---	--------	-----	---	----------------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERS SINGAPORE 048623			Ref: CS/SMO22001314/Ktf3 Date: 11/02/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 9275B		Veh. Inspected	FBR 122M
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2200370/GPL		Excess (\$)	0.00
Assign From	GRACE TEO		Assign Date	11/02/2022
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
Accident Date	25/01/2022		Inspection Date	11/02/2022
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				