

Our Ref : SND1222H / TP#1525
Your Ref : SJM801T

WITHOUT PREJUDICE

Date : 19TH SEPT 2022

AIG ASIA PACIFIC INSURANCE PTE. LTD.
AIG BUILDING
78 Shenton Way #07-16
Singapore 079120

Attention: Motor Claims Department

**ACCIDENT INVOLVING SND1222H & SJM801T ON 05/02/2022
ALONG 160 SIXTH AVE SINGAPORE 276537**

We refer to the above captioned.

We are claiming the below followings:

- Cost of Repair (incl. of GST)	S\$ 37,627.31
- Loss of Use	S\$ 18,840.00 (\$120.00 x 157 Days)
- LTA / GIA Search Fee	S\$ 2.00
Grand Total	S\$ 56,469.31
	=====

If you have any enquiries, please contact our representative, Mr. Joseph at 6481-1522 or email joseph@ow.sg

All payment is to be issued direct to **Optima Werkz Pte Ltd.**

Your prompt attention is most grateful and look forward to your speedy settlement.

Yours faithfully

OPTIMA WERKZ PTE LTD
Encl.

This is a computer generated printout and no signature is required.

Optima Werkz Pte Ltd

10 Ang Mo Kio Industrial Park 2A #01-05, Singapore 568047

Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#08-16 AIG BUILDING
SINGAPORE 079120

Tel: 64191000
Fax: 68357416

INV NO. : 322201082
INVOICE DATE : 10/09/2022
REF : TP#1525
VEH NO. : SND1222H
MAKE : TESLA
CAR MODEL : TESLA MODEL 3
CURRENT MILEAGE:
ADVISOR : TING AN
TERMS : COD
MECHANIC :

DESCRIPTION	QTY	UOM	Tax Code	U/P SGD	AMT SGD
REAR BOOTLID	1	PCS	SR	656.07	656.07
REAR BOOTLID "DUAL MOTOR" EMBLEM	1	PCS	SR	26.92	26.92
REAR BOOTLID "TESLA" EMBLEM	1	PCS	SR	33.64	33.64
REAR BOOTLID LAMP RH	1	PCS	SR	159.81	159.81
REAR BUMPER	1	PCS	SR	597.20	597.20
REAR BUMPER SIDE BRACKET RH	1	PCS	SR	6.73	6.73
REAR BUMPER CENTRE BRACKET	1	PCS	SR	47.11	47.11
REAR BUMPER LOWER LIP	1	PCS	SR	126.17	126.17
REAR BUMPER UNDER COVER	1	PCS	SR	185.05	185.05
REAR BUMPER REFLECTOR RH	1	PCS	SR	18.50	18.50
REAR BUMPER PARKING SENSOR	1	PCS	SR	142.99	142.99
REAR BUMPER PARKING SENSOR BRACKET	1	PCS	SR	4.20	4.20
REAR TAIL LAMP RH	1	PCS	SR	252.33	252.33
REAR TAIL LAMP BRACKET RH	1	PCS	SR	2.52	2.52
REAR TAIL LAMP REFLECTOR RH	1	PCS	SR	32.81	32.81
REAR END PANEL	1	PCS	SR	403.74	403.74
REAR FENDER RH	1	PCS	SR	1,118.69	1,118.69
REAR FENDER QUARTER GLASS RH	1	PCS	SR	252.33	252.33
REAR FENDER INNER PANEL RH	1	PCS	SR	100.94	100.94
FRONT BONNET	1	PCS	SR	597.20	597.20
FRONT BONNET HINGE LH	1	PCS	SR	67.29	67.29
FRONT BONNET HINGE RH	1	PCS	SR	67.29	67.29
FRONT BONNET STRUT LH	1	PCS	SR	47.11	47.11
FRONT BONNET STRUT RH	1	PCS	SR	47.11	47.11
FRONT BONNET "TESLA" EMBLEM	1	PCS	SR	43.74	43.74
FRONT BONNET LOCK	1	PCS	SR	159.81	159.81
FRONT BONNET LOCK ACTUATOR ASSY	1	PCS	SR	96.73	96.73
FRONT BONNET STRIKER	1	PCS	SR	2.52	2.52
FRONT LUGGAGE COMPARTMENT	1	PCS	SR	58.04	58.04
FRONT LUGGAGE COMPARTMENT MAT	1	PCS	SR	67.29	67.29
FRONT WINDSCREEN GLASS	1	PCS	SR	706.55	706.55
FRONT DASHBOARD	1	PCS	SR	1,068.21	1,068.21
FRONT PASSENGER AIRBAG	1	PCS	SR	580.32	580.32
FRONT STEERING WHEEL AIRBAG	1	PCS	SR	403.74	403.74

Optima Werkz Pte Ltd

10 Ang Mo Kio Industrial Park 2A #01-05, Singapore 568047

Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#08-16 AIG BUILDING
SINGAPORE 079120

Tel: 64191000
Fax: 68357416

INV NO. : 322201082
INVOICE DATE : 10/09/2022
REF : TP#1525
VEH NO. : SND1222H
MAKE : TESLA
CAR MODEL : TESLA MODEL 3
CURRENT MILEAGE:
ADVISOR : TING AN
TERMS : COD
MECHANIC :

DESCRIPTION	QTY	UOM	Tax Code	U/P SGD	AMT SGD
FRONT AIRBAG CONTROL UNIT	1	PCS	SR	504.68	504.68
FRONT AIRBAG SENSOR	1	PCS	SR	105.98	105.98
FRONT SAFETY BELT LH	1	PCS	SR	142.99	142.99
FRONT SAFETY BELT RH	1	PCS	SR	142.99	142.99
FRONT HEADLAMP LH	1	PCS	SR	1,177.57	1,177.57
FRONT HEADLAMP RH	1	PCS	SR	1,177.57	1,177.57
FRONT HEADLAMP LOWER BRACKET LH	1	PCS	SR	6.73	6.73
FRONT HEADLAMP LOWER BRACKET RH	1	PCS	SR	6.73	6.73
FRONT BUMPER	1	PCS	SR	597.20	597.20
FRONT BUMPER SIDE BRACKET LH	1	PCS	SR	8.42	8.42
FRONT BUMPER SIDE BRACKET RH	1	PCS	SR	8.42	8.42
FRONT BUMPER CENTRE UPPER BRACKET LH	1	PCS	SR	10.94	10.94
FRONT BUMPER CENTRE UPPER BRACKET RH	1	PCS	SR	10.94	10.94
FRONT BUMPER UPPER BRACKET LH	1	PCS	SR	1.68	1.68
FRONT BUMPER UPPER BRACKET RH	1	PCS	SR	1.68	1.68
FRONT BUMPER LOWER GRILLE	1	PCS	SR	92.52	92.52
FRONT BUMPER FOG LAMP LH	1	PCS	SR	243.93	243.93
FRONT BUMPER FOG LAMP RH	1	PCS	SR	243.93	243.93
FRONT BUMPER REINFORCEMENT	1	PCS	SR	243.93	243.93
FRONT BUMPER ABSORBER FOAM	1	PCS	SR	42.06	42.06
FRONT BUMPER REINFORCEMENT CRUSH CAN LH	1	PCS	SR	47.11	47.11
FRONT BUMPER REINFORCEMENT CRUSH CAN RH	1	PCS	SR	47.11	47.11
FRONT BUMPER LOWER REINFORCEMENT	1	PCS	SR	92.52	92.52
FRONT BUMPER LOWER REINFORCEMENT CRUSH CAN LH	1	PCS	SR	53.83	53.83
FRONT BUMPER LOWER REINFORCEMENT CRUSH CAN RH	1	PCS	SR	53.83	53.83
FRONT SUPPORT BEAM	1	PCS	SR	664.49	664.49
FRONT SUPPORT BEAM BRACKET LH	1	PCS	SR	6.73	6.73
FRONT SUPPORT BEAM BRACKET RH	1	PCS	SR	6.73	6.73
FRONT BUMPER UNDER COVER	1	PCS	SR	168.23	168.23
FRONT BUMPER PARKING SENSOR	1	PCS	SR	857.95	857.95
FRONT BUMPER PARKING SENSOR BRACKET	1	PCS	SR	25.22	25.22
FRONT BUMPER WIRING HARNESS	1	PCS	SR	84.11	84.11
FRONT HEADLAMP WIRING HARNESS	1	PCS	SR	79.91	79.91
FRONT AMBIENT AIR SENSOR	1	PCS	SR	1.65	1.65

Optima Werkz Pte Ltd

10 Ang Mo Kio Industrial Park 2A #01-05, Singapore 568047

Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#08-16 AIG BUILDING
SINGAPORE 079120

Tel: 64191000
Fax: 68357416

INV NO. : 322201082
INVOICE DATE : 10/09/2022
REF : TP#1525
VEH NO. : SND1222H
MAKE : TESLA
CAR MODEL : TESLA MODEL 3
CURRENT MILEAGE:
ADVISOR : TING AN
TERMS : COD
MECHANIC :

DESCRIPTION	QTY	UOM	Tax Code	U/P SGD	AMT SGD
FRONT AIR VENT ASSY	1	PCS	SR	168.23	168.23
FRONT RADAR SENSOR	1	PCS	SR	311.21	311.21
FRONT RADAR SENSOR BRACKET	1	PCS	SR	4.20	4.20
FRONT RADAR SENSOR SUPPORT BRACKET	1	PCS	SR	6.73	6.73
FRONT AIRCON CONDENSER	1	PCS	SR	378.50	378.50
FRONT AIRCON CONDENSER COOLING FAN & SHROULD	1	PCS	SR	336.45	336.45
FRONT AIRCON CONDENSER PRESSURE PIPE	1	PCS	SR	227.11	227.11
FRONT AIRCON CONDENSER DISCHARGE PIPE	1	PCS	SR	201.87	201.87
FRONT FENDER LH	1	PCS	SR	403.74	403.74
FRONT FENDER RH	1	PCS	SR	403.74	403.74
FRONT FENDER INNER SHIELD LH	1	PCS	SR	105.14	105.14
FRONT FENDER INNER SHIELD RH	1	PCS	SR	105.14	105.14
FRONT RIM RH	1	PCS	SR	908.42	908.42
FRONT SUBFRAME ASSY	1	PCS	SR	1,059.81	1,059.81
FRONT ABSORBER RH	1	PCS	SR	386.92	386.92
FRONT UPPER ARM RH	1	PCS	SR	105.14	105.14
FRONT LOWER ARM RH	1	PCS	SR	210.28	210.28
FRONT KNUCKLE ARM RH	1	PCS	SR	378.50	378.50
FRONT WHEEL BEARING HUB RH	1	PCS	SR	134.58	134.58
FRONT FENDER SUPPORT BRACKET LH	1	PCS	SR	21.02	21.02
FRONT FENDER SUPPORT BRACKET RH	1	PCS	SR	21.02	21.02
FRONT CENTRE UNDER COVER	1	PCS	SR	201.87	201.87
FRONT HORN SENSOR ASSY	1	PCS	SR	40.37	40.37
FRONT WIPER AIR GRILLE	1	PCS	SR	40.37	40.37
FRONT SEAT BUCKLE LH	1	PCS	SR	67.29	67.29
FRONT SEAT BUCKLE RH	1	PCS	SR	67.29	67.29
HIGH VOLTAGE BATTERY PYROFUSE	1	PCS	SR	37.92	37.94
FRONT DASHBOARD WIRING HARNESS	1	PCS	SR	160.99	160.99
FRONT STEERING RACK	1	PCS	SR	2,405.61	2,405.61
REAR BUMPER REINFORCEMENT	1	PCS	SR	243.93	243.93
REAR AUDIO SUBWOOFER ASSEMBLY	1	PCS	SR	294.39	294.39
REAR AUDIO AMPLIFIER	1	PCS	SR	328.04	328.04
FRONT DOOR OUTER MOULDING LH	1	PCS	SR	79.91	79.91
FRONT DOOR OUTER MOULDING RH	1	PCS	SR	79.91	79.91

Optima Werkz Pte Ltd

10 Ang Mo Kio Industrial Park 2A #01-05, Singapore 568047

Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#08-16 AIG BUILDING
SINGAPORE 079120

Tel: 64191000
Fax: 68357416

INV NO. : 322201082
INVOICE DATE : 10/09/2022
REF : TP#1525
VEH NO. : SND1222H
MAKE : TESLA
CAR MODEL : TESLA MODEL 3
CURRENT MILEAGE:
ADVISOR : TING AN
TERMS : COD
MECHANIC :

DESCRIPTION	QTY	UOM	Tax Code	U/P SGD	AMT SGD
REAR DOOR OUTER MOULDING LH	1	PCS	SR	79.91	79.91
REAR DOOR OUTER MOULDING RH	1	PCS	SR	79.91	79.91
FRONT DOOR UPPER MOULDING LH	1	PCS	SR	227.11	227.11
FRONT DOOR UPPER MOULDING RH	1	PCS	SR	227.11	227.11
REAR BOOTLID INNER TRIM CLIPS	1	PCS	SR	50.00	50.00
REAR BUMPER CLIPS	1	PCS	SR	60.00	60.00
REAR END PANEL JOINT SEALANT	1	PCS	SR	30.00	30.00
REAR FENDER QUARTER GLASS SEALANT RH	1	PCS	SR	40.00	40.00
FRONT WINDSCREEN GLASS SEALANT	1	PCS	SR	40.00	40.00
FRONT BUMPER CLIPS	1	PCS	SR	60.00	60.00
FRONT NUMBER PLATE & HOLDER	1	PCS	SR	45.00	45.00
FRONT TYRE RH	1	PCS	SR	500.00	500.00
FRONT FENDER INNER SHIELD CLIPS LH	1	PCS	SR	40.00	40.00
FRONT FENDER INNER SHIELD CLIPS RH	1	PCS	SR	40.00	40.00
PPF WRAP FOR AFFECTED AREAS	1	PCS	SR	2,800.00	2,800.00
LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.	1	JOB	SR	2,000.00	2,000.00
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.	1	JOB	SR	2,200.00	2,200.00
LABOUR CHARGES TO REMOVE & REPLACE FRONT & REAR PARKING SENSOR	1	JOB	SR	120.00	120.00
LABOUR CHARGES TO REMOVE & REFIX FRONT BUMPER WIRIN HARNESS & ETC. TO EFFECT REPLACE OF FRONT BUMPER	1	JOB	SR	60.00	60.00
LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.	1	JOB	SR	120.00	120.00
LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS LH & ETC.	1	JOB	SR	60.00	60.00
LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT KNUCKLE ARM RH, FRONT UPPER & LOWER ARM RH, FRONT WHEEL BEARING RH & ETC.	1	JOB	SR	220.00	220.00
LABOUR CHARGES TO REMOVE & REPLACE FRONT SAFETY BELT LH & RH, FRONT PASSENGER AIRBAG, FRONT STEERING WHEEL AIRBAG & ETC.	1	JOB	SR	280.00	280.00
LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT DASHBOARD & ETC.	1	JOB	SR	250.00	250.00
TO DIAGNOSE & RESET AIRBAG CONTROL UNIT.	1	JOB	SR	200.00	200.00

Optima Werkz Pte Ltd

10 Ang Mo Kio Industrial Park 2A #01-05, Singapore 568047

Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#08-16 AIG BUILDING
SINGAPORE 079120

Tel: 64191000
Fax: 68357416

INV NO. : 322201082
INVOICE DATE : 10/09/2022
REF : TP#1525
VEH NO. : SND1222H
MAKE : TESLA
CAR MODEL : TESLA MODEL 3
CURRENT MILEAGE:
ADVISOR : TING AN
TERMS : COD
MECHANIC :

DESCRIPTION	QTY	UOM	Tax Code	U/P SGD	AMT SGD
TO DIAGNOSE FAULT CODE & RESET MEMORY.	1	JOB	SR	120.00	120.00
TO WHEEL ALIGNMENT & BALANCING.	1	JOB	SR	20.00	20.00
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	1	JOB	SR	40.00	40.00
TO TUFF KOTE & UNDERSEAL MATERIALS.	1	JOB	SR	90.00	90.00

Remarks: DOA: 05/02/2022@19:00HRS

CLAIMANT: EAYRS NICHOLAS PETER / EAYRS DAWN SIAW-CHING

TP VEHICLE: SJM801T

Singapore Dollars: Thirty-Seven Thousand Six Hundred Twenty-Seven And Cent Thirty-One Only

SUB TOTAL SGD 35,165.71
GST 7.00% SGD 2,461.60
TOTAL SGD 37,627.31
OUTSTANDING SGD 37,627.31

Tax Legend:

SR - Standard Rated ZR - Zero Rated OS - Out of Scope

Tax Amount 35,165.71

I/We confirm that I/We incurred the repair costs herein and will observe my/our agreement with the repairs. I/We declare the repairs for above vehicle have been completed to my/our satisfaction.

- 1) New parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of one (1) year or mileage up to 30,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 2) Recon Parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of six (6) months or mileage up to 10,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 3) Goods sold are not refundable/returnable.
- 4) Original Invoice is only valid when the payment is acknowledge receipt by Optima Werkz Pte Ltd. Interest of 2% per month will be charged on any outstanding amount



Opt for a more convenient and quicker way to pay via Bank Transfer or PayNow:

Beneficiary Name: Optima Werkz Pte Ltd

Beneficiary Bank Name: DBS Bank Ltd

Bank Account No.:0039441282

Swift Code: DBSSSGSG

OR

PayNow UEN: 201212455WDB1

Note: Please include your invoice number under the reference section

Customer Acknowledgement

For Optima Werkz Pte Ltd

Customer Name and Signature

Authorised Signature

INSURER ENQUIRY

Find

insurer

Vehicle reg. no.

SJM801T

Date of Accident

05/02/2022 

Reset

% RESULT & RECEIPT

SN01222H Tes/a Models

TP Insurer Enquiry

Insurance **AIG Asia Pacific Insurance Pte....**Period of Insurance **30/06/2021 - 29/06/2022**Requested By **Ary Chua (OPTIMA WERKZ PTE...**Requested Date **07/02/2022 10:21**

Payment details

Request Amount: **S\$1.87**GST Amount: **S\$0.13**Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**

AUTHORISATION TO ACT

I/We, Eayrs Nicholas Peter ("the third party claimant") of
3 Ming Teck Park S277371 (address), owner of
SND1222H (vehicle no.) hereby authorize **OPTIMA WERKZ PTE LTD** ("the
workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of
use ("claim") for my vehicle no. SND1222H that was damaged pursuant to the accident
which occurred on 05/02/2022 (date) along 160 Sixth Ave S276537
_____ (location) involving vehicle no/s SJM8017 ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they
deem fit and the workshop is further authorized to receive payment further to settlement of
my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability basis insofar as the driver/owner/insurers
of the other vehicle/s is concerned.

Dated this 7th (day) of February (month) 2022 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)