

ASS. REQ. BY:

REF:

AIG/ 220013151He

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

9/19 @ 35,165.71 cabw

Veh No:

SND 122214

Yr Regn:

12
21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Tesla Model 3 c.c.

Colour

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

2875

T/Radio: Insured / Std / NI / NA

Eng/No:

R

C/No:

LW317 ECG MC 384844

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

5/12/22

D.O.I.

11/2/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S & FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Date: 10/02/2022
 Vehicle No: SND1222H
 Model: TESLA MODEL 3 PERFORMANCE
 Chassis: LRW3F7EC6MC384844-2021
 Reg.Year: 2021

Third Party Insurer: AIG
 Third Party Veh No: SJM801T
 Date of Accident: 05/02/2022
 Estimator: TING AN
 Surveyor:

Not Authorized
Penalty B4pain
24 days
\$ 35,165.71

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID	1		<i>Bt</i> \$728.97
2	REAR BOOTLID "DUAL MOTOR" EMBLEM	1		<i>mc</i> \$29.91
3	REAR BOOTLID "TESLA" EMBLEM	1		<i>mc</i> \$37.38
4	REAR BOOTLID INNER TRIM BOARD	1		<i>sm</i> \$46.73
5	REAR BOOTLID LAMP RH	1		<i>Not / cm</i> \$177.57
6	REAR BUMPER	1		<i>Bu / cm</i> \$663.55
7	REAR BUMPER SIDE BRACKET RH	1		<i>Di</i> \$7.48
8	REAR BUMPER CENTER BRACKET	1		<i>cm</i> \$52.34
9	REAR BUMPER LOWER LIP	1		<i>Di / cm</i> \$140.19
10	REAR BUMPER UNDER COVER	1		<i>cm</i> \$205.61
11	REAR BUMPER REFLECTOR RH	1		<i>Bu</i> \$20.56
12	REAR BUMPER PARKING SENSOR	<i>31</i>	\$158.88	\$476.64
13	REAR BUMPER PARKING SENSOR BRACKET	<i>31</i>	\$4.67	<i>mc</i> \$14.01
14	REAR TAIL LAMP RH	1		<i>cm</i> \$280.37
15	REAR TAIL LAMP BRACKET RH	1		<i>cm</i> \$2.80
16	REAR TAIL LAMP REFELCTOR RH	1		<i>mi</i> \$36.45
17	REAR END PANEL	1		<i>Bt</i> \$448.60
18	REAR FENDER RH	1		<i>Bu</i> \$1,242.99
19	REAR FENDER QUARTER GLASS RH	1		<i>mc</i> \$280.37
20	REAR FENDER INNER SHIELD RH	1		<i>sm</i> \$116.82
21	REAR FENDER INNER PANEL RH	1		<i>Bt</i> \$112.15
22	FRONT BONNET	1		<i>Bt</i> \$663.55
23	FRONT BONNET HINGE LH	1		<i>Di</i> \$74.77
24	FRONT BONNET HINGE RH	1		<i>Di</i> \$74.77
25	FRONT BONNET STRUT LH	1		<i>Tr</i> \$52.34
26	FRONT BONNET STRUT RH	1		<i>Tr</i> \$52.34
27	FRONT BONNET "TESLA" EMBLEM	1		<i>mc</i> \$48.60
28	FRONT BONNET LOCK	1		<i>Bt</i> \$177.57
29	FRONT BONNET LOCK ACTUATOR ASSY	1		<i>Tr</i> \$107.48
30	FRONT BONNET STRIKER	1		<i>Di</i> \$2.80
31	FRONT LUGGAGE COMPARTMENT	1		<i>Mc / Bu</i> \$64.49
32	FRONT LUGGAGE COMPARTMENT MAT	1		<i>mc</i> \$74.77
33	FRONT WINDSCREEN GLASS	1		<i>cm</i> \$785.05
34	FRONT DASHBOARD	1		<i>Tr</i> \$1,186.90
35	FRONT PASSENGER AIRBAG	1		<i>Bu / cm</i> \$644.80
36	FRONT STEERING WHEEL AIRBAG	1		<i>mc</i> \$448.60
37	FRONT AIRBAG CONTROL UNIT	1		<i>mc</i> \$560.75

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10/02/2022
Vehicle No: SND1222H
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7EC6MC384844-2021
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SJM801T
Date of Accident: 05/02/2022
Estimator: TING AN
Surveyor:

38	FRONT AIRBAG SENSOR	2	\$58.88	\$117.76
39	FRONT SAFETY BELT LH	1		\$158.88
40	FRONT SAFETY BELT RH	1		\$158.88
41	FRONT HEADLAMP LH	1		\$1,308.41
42	FRONT HEADLAMP RH	1		\$1,308.41
43	FRONT HEADLAMP LOWER BRACKET LH	1		\$7.48
44	FRONT HEADLAMP LOWER BRACKET RH	1		\$7.48
45	FRONT BUMPER	1		\$663.55
46	FRONT BUMPER TOWING COVER	1		\$14.95
47	FRONT BUMPER SIDE BRACKET LH	1		\$9.35
48	FRONT BUMPER SIDE BRACKET RH	1		\$9.35
49	FRONT BUMPER CENTER UPPER BRACKET LH	1		\$12.15
50	FRONT BUMPER CENTER UPPER BRACKET RH	1		\$12.15
51	FRONT BUMPER UPPER BRACKET LH	1		\$1.87
52	FRONT BUMPER UPPER BRACKET RH	1		\$1.87
53	FRONT BUMPER LOWER GRILLE	1		\$102.80
54	FRONT BUMPER FOG LAMP LH	1		\$271.03
55	FRONT BUMPER FOG LAMP RH	1		\$271.03
56	FRONT BUMPER REINFORCEMENT	1		\$271.03
57	FRONT BUMPER ABSORBER FOAM	1		\$46.73
58	FRONT BUMPER REINFORCEMENT CRUSH CAN LH	1		\$52.34
59	FRONT BUMPER REINFORCEMENT CRUSH CAN RH	1		\$52.34
60	FRONT BUMPER LOWER REINFORCEMENT	1		\$102.80
61	FRONT BUMPER LOWER REINFORCEMENT CRUSH CAN LH	1		\$59.81
62	FRONT BUMPER LOWER REINFORCEMENT CRUSH CAN RH	1		\$59.81
63	FRONT SUPPORT BEAM	1		\$738.32
64	FRONT SUPPORT BEAM BRACKET LH	1		\$7.48
65	FRONT SUPPORT BEAM BRACKET RH	1		\$7.48
66	FRONT BUMPER UNDER COVER	1		\$186.92
67	FRONT BUMPER PARKING SENSOR	6	\$158.88	\$953.28
68	FRONT BUMPER PARKING SENSOR BRACKET	6	\$4.67	\$28.02
69	FRONT BUMPER WIRING HARNESS	1		\$93.46
70	FRONT HEADLAMP WIRING HARNESS	1		\$88.79
71	FRONT AMBIENT AIR SENSOR	1		\$1.83
72	FRONT AIR VENT ASSY	1		\$186.92
73	FRONT RADAR SENSOR	1		\$345.79
74	FRONT RADAR SENSOR BRACKET	1		\$4.67
75	FRONT RADAR SENSOR SUPPORT BRACKET	1		\$7.48
76	FRONT AIRCON CONDENSER	1		\$420.56

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10/02/2022
 Vehicle No: SND1222H
 Model: TESLA MODEL 3 PERFORMANCE
 Chassis: LRW3F7EC6MC384844-2021
 Reg Year: 2021

Third Party Insurer: AIG
 Third Party Veh No: SJM801T
 Date of Accident: 05/02/2022
 Estimator: TING AN
 Surveyor:

77	FRONT AIRCON CONDENSER COOLING FAN & SHROULD	1	CM	\$373.83	✓
78	FRONT AIRCON CONDENSER PRESSURE PIPE	1	nd	\$252.34	✓
79	FRONT AIRCON CONDENSER DISCHARGE PIPE	1	nd	\$224.30	✓
80	FRONT FENDER LH	1	Bu	\$448.60	✓
81	FRONT FENDER RH	1	Bu	\$448.60	✓
82	FRONT FENDER INNER SHIELD LH	1	CM	\$116.82	✓
83	FRONT FENDER INNER SHIELD RH	1	CM	\$116.82	✓
84	FRONT RIM RH	1	nd	\$1,009.35	✓
85	FRONT SUBFRAME ASSY	1	Bu	\$1,177.57	✓
86	FRONT AABSORBER RH	1	Bu	\$429.91	✓
87	FRONT UPPER ARM RH	1	Dis	\$116.82	✓
88	FRONT LOWER ARM RH	1	Bu	\$233.64	✓
89	FRONT KNUCKLE ARM RH	1	Bu	\$420.56	✓
90	FRONT WHEEL BEARING HUB RH	1	nd	\$149.53	✓
91	FRONT DOOR LH	1		REPAIR	
92	FRONT DOOR RH	1		REPAIR	
				SUB TOTAL	\$23,813.02
				LESS 10%	-\$2,381.30
				PARTS TOTAL	\$21,431.72

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID INNER TRIM CLIPS	1		<i>nee</i> \$50.00
2	REAR BUMPER CLIPS	1		<i>nee</i> \$60.00
3	REAR END PANEL JOINT SEALANT	1		<i>nee</i> \$80.00
4	REAR FENDER QUARTER GLASS SEALANT RH	1		<i>nee</i> \$60.00
5	REAR FENDER INNER SHIELD CLIPS RH	1		<i>nee</i> \$40.00
6	FRONT WINDSCREEN GLASS SEALANT	1		<i>nee</i> \$80.00
7	FRONT BUMPER CLIPS	1		<i>nee</i> \$60.00
8	FRONT NUMBER PLATE & HOLDER	1		<i>nee</i> \$50.00
9	FRONT TYRE RH	1		DAM \$500.00
10	FRONT FENDER INNER SHIELD CLIPS LH	1		<i>nee</i> \$40.00
11	FRONT FENDER INNER SHIELD CLIPS RH	1		<i>nee</i> \$40.00
12	PPF WRAP FOR AFFECTED AREAS	1	<i>(Bill)</i>	\$3,000.00
			S/N TOTAL	\$4,060.00

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10/02/2022
Vehicle No: SND1222H
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7EC6MC384844-2021
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SJM801T
Date of Accident: 05/02/2022
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

2000
\$3,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER, REAR FENDER RH, REAR END PANEL, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT DOOR LH, FRONT DOOR RH & ETC.

2200
\$3,000.00

LABOUR CHARGES TO REMOVE & REPLACE FRONT & REAR PARKING SENSOR.

\$200.00 1200

LABOUR CHARGES TO REMOVE & REFIX FRONT BUMPER WIRING HARNESS & ETC. TO EFFECT REPLACE OF FRONT BUMPER.

\$150.00 600

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & UNHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

\$300.00 1200

LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS LH & ETC.

\$150.00 600

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT KNUCKLE ARM RH, FRONT UPPER & LOWER ARM RH, FRONT WHEEL BEARING RH & ETC.

\$350.00 2200

LABOUR CHARGES TO REMOVE & REPLACE FRONT SAFETY BELT LH & RH, FRONT PASSENGER AIRBAG, FRONT STEERING WHEEL AIRBAG & ETC.

\$500.00 2800

LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT DASHBOARD & ETC.

\$400.00 2500

TO DIAGNOSIS & RESET AIRBAG CONTROL UNIT.

\$300.00 2000

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

\$200.00 1200

TO WHEEL ALIGNMENT & BALANCING.

\$100.00 200

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$120.00 400

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10/02/2022
Vehicle No: SND1222H
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7EC6MC384844-2021
Reg. Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SJM801T
Date of Accident: 05/02/2022
Estimator: TING AN
Surveyor:

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$250.00

TO REALIGN CHASSIS & ETC.

\$300.00

LABOUR TOTAL \$9,320.00

TOTAL \$34,811.72

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 01/06/2022
Vehicle No: SND1222H
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7EC6MC384844-2021
Reg. Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SJM801T
Date of Accident: 05/02/2022

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT FENDER SUPPORT BRACKET LH	1		CM \$23.36
2	FRONT FENDER SUPPORT BRACKET RH	1		CM \$23.36
3	FRONT CENTER UNDER COVER	1		CM \$224.30
4	FRONT HORN SENSOR ASSY	1		PL \$44.86
5	FRONT WIPER AIR GRILLE	1		PL \$44.86
6	FRONT SEAT BELT BUCKLE LH	1		JM \$74.77
7	FRONT SEAT BELT BUCKLE RH	1		JM \$74.77
8	HIGH VOLTAGE BATTERY PYROFUSE	1		PL \$42.18
9	FRONT DASHBOARD WIRING HARNESS	1		JM \$178.88
10	FRONT STEERING RACK	1		B71 JM \$2,672.90
11	REAR BUMPER REINFORCEMENT	1		PL \$271.03
12	REAR AUDIO SUBWOOFER ASSEMBLY	1		MB BR \$327.10
13	REAR AUDIO AMPLIFIER	1		PL \$364.49
SUB TOTAL				\$4,366.86
LESS 10%				-\$436.69
PARTS TOTAL				\$3,930.17

TING AN TOTAL \$3,930.17

Head office

8 Keng Chong Road Singapore 159143
Tel: (+65) 6472 1213 | Fax: (+65) 6472 2132

Branch

6A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6464 1819 | Fax: (+65) 6463 1013

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6467 1122 | Fax: (+65) 6467 1011



Date: 14/07/2022

Third Party Insurer: AIG

Vehicle No: SND1222H

Third Party Veh No: SJM801T

Model: TESLA MODEL 3 PERFORMANCE

Date of Accident: 05/02/2022

Chassis: LRW3F7EC6MC384844-2021

Reg.Year: 2021

SUPPLEMENTARY (1)

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR OUTER MOULDING LH	1		\$88.79
2	FRONT DOOR OUTER MOULDING RH	1		\$88.79
3	REAR DOOR OUTER MOULDING LH	1		\$88.79
4	REAR DOOR OUTER MOULDING RH	1		\$88.79
5	FRONT DOOR UPPER MOULDING LH	1		\$252.34
6	FRONT DOOR UPPER MOULDING RH	1		\$252.34
SUB TOTAL				\$859.84
LESS 10%				-\$85.98
PARTS TOTAL				\$773.86

TING AN

TOTAL

\$773.86

Finalise.

Parts : \$20976.68

Supp : \$3930.17

Supp(l): \$773.86

Matt : \$5905

Labour : \$5780

P/e : \$37365.71

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9019 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6491 1522 | Fax: (+65) 6461 1011

