

Date: 10/02/2022
Vehicle No: SND1222H
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7EC6MC384844-2021
Reg.Year: 2021

Not Withheld
Running B4 repair
24 days

Third Party Insurer: AIG
Third Party Veh No: SJM801T
Date of Accident: 05/02/2022
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID	1		<i>Bu</i> \$728.97
2	REAR BOOTLID "DUAL MOTOR" EMBLEM	1		<i>bu</i> \$29.91
3	REAR BOOTLID "TESLA" EMBLEM	1		<i>bu</i> \$37.38
4	REAR BOOTLID INNER TRIM BOARD	1		<i>bu</i> \$46.73
5	REAR BOOTLID LAMP RH	1		<i>bu / bu</i> \$177.57
6	REAR BUMPER	1		<i>Bu / cm</i> \$663.55
7	REAR BUMPER SIDE BRACKET RH	1		<i>bu</i> \$7.48
8	REAR BUMPER CENTER BRACKET	1		\$52.34
9	REAR BUMPER LOWER LIP	1		<i>bu / bu</i> \$140.19
10	REAR BUMPER UNDER COVER	1		\$205.61
11	REAR BUMPER REFLECTOR RH	1		<i>bu</i> \$20.56
12	REAR BUMPER PARKING SENSOR	<i>2 / 1</i>	\$158.88	\$476.64
13	REAR BUMPER PARKING SENSOR BRACKET	3	\$4.67	\$14.01
14	REAR TAIL LAMP RH	1		<i>cm</i> \$280.37
15	REAR TAIL LAMP BRACKET RH	1		\$2.80
16	REAR TAIL LAMP REFELCTOR RH	1		<i>bu</i> \$36.45
17	REAR END PANEL	1		\$448.60
18	REAR FENDER RH	1		<i>bu</i> \$1,242.99
19	REAR FENDER QUARTER GLASS RH	1		<i>bu</i> \$280.37
20	REAR FENDER INNER SHIELD RH	1		<i>bu</i> \$116.82
21	REAR FENDER INNER PANEL RH	1		\$112.15
22	FRONT BONNET	1		<i>Bu</i> \$663.55
23	FRONT BONNET HINGE LH	1		<i>bu</i> \$74.77
24	FRONT BONNET HINGE RH	1		<i>bu</i> \$74.77
25	FRONT BONNET STRUT LH	1		<i>bu</i> \$52.34
26	FRONT BONNET STRUT RH	1		<i>bu</i> \$52.34
27	FRONT BONNET "TESLA" EMBLEM	1		<i>bu</i> \$48.60
28	FRONT BONNET LOCK	1		<i>Bu</i> \$177.57
29	FRONT BONNET LOCK ACTUATOR ASSY	1		<i>bu</i> \$107.48
30	FRONT BONNET STRIKER	1		<i>bu</i> \$2.80
31	FRONT LUGGAGE COMPARTMENT	1		<i>bu</i> \$64.49
32	FRONT LUGGAGE COMPARTMENT MAT	1		<i>bu</i> \$74.77
33	FRONT WINDSCREEN GLASS	1		<i>cm</i> \$785.05
34	FRONT DASHBOARD	1		<i>bu</i> \$1,186.90
35	FRONT PASSENGER AIRBAG	1		<i>bu</i> \$644.80
36	FRONT STEERING WHEEL AIRBAG	1		<i>bu</i> \$448.60
37	FRONT AIRBAG CONTROL UNIT	1		<i>bu</i> \$560.75

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10/02/2022
Vehicle No: SND1222H
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7EC6MC384844-2021
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SJM801T
Date of Accident: 05/02/2022
Estimator: TING AN
Surveyor:

38	FRONT AIRBAG SENSOR	2	\$58.88	\$117.76	✓
39	FRONT SAFETY BELT LH	1		\$158.88	✓
40	FRONT SAFETY BELT RH	1		Jm \$158.88	✓
41	FRONT HEADLAMP LH	1		\$1,308.41	✓
42	FRONT HEADLAMP RH	1		CM \$1,308.41	✓
43	FRONT HEADLAMP LOWER BRACKET LH	1		\$7.48	✓
44	FRONT HEADLAMP LOWER BRACKET RH	1		\$7.48	✓
45	FRONT BUMPER	1		Bj \$663.55	✓
46	FRONT BUMPER TOWING COVER	1		Pu \$14.95	x
47	FRONT BUMPER SIDE BRACKET LH	1		Diy \$9.35	✓
48	FRONT BUMPER SIDE BRACKET RH	1		Diy \$9.35	✓
49	FRONT BUMPER CENTER UPPER BRACKET LH	1		Bj \$12.15	✓
50	FRONT BUMPER CENTER UPPER BRACKET RH	1		Bj \$12.15	✓
51	FRONT BUMPER UPPER BRACKET LH	1		Miy \$1.87	✓
52	FRONT BUMPER UPPER BRACKET RH	1		Miy \$1.87	✓
53	FRONT BUMPER LOWER GRILLE	1		CM \$102.80	✓
54	FRONT BUMPER FOG LAMP LH	1		\$271.03	✓
55	FRONT BUMPER FOG LAMP RH	1		Bu \$271.03	✓
56	FRONT BUMPER REINFORCEMENT	1		Bj \$271.03	✓
57	FRONT BUMPER ABSORBER FOAM	1		CM \$46.73	✓
58	FRONT BUMPER REINFORCEMENT CRUSH CAN LH	1		Bj \$52.34	✓
59	FRONT BUMPER REINFORCEMENT CRUSH CAN RH	1		Bj \$52.34	✓
60	FRONT BUMPER LOWER REINFORCEMENT	1		Bj \$102.80	✓
61	FRONT BUMPER LOWER REINFORCEMENT CRUSH CAN LH	1		Bj \$59.81	✓
62	FRONT BUMPER LOWER REINFORCEMENT CRUSH CAN RH	1		Bj \$59.81	✓
63	FRONT SUPPORT BEAM	1		Bj \$738.32	✓
64	FRONT SUPPORT BEAM BRACKET LH	1		CM \$7.48	✓
65	FRONT SUPPORT BEAM BRACKET RH	1		CM \$7.48	✓
66	FRONT BUMPER UNDER COVER	1		CM \$186.92	✓
67	FRONT BUMPER PARKING SENSOR	6	\$158.88	\$953.28	✓
68	FRONT BUMPER PARKING SENSOR BRACKET	6	\$4.67	\$28.02	✓
69	FRONT BUMPER WIRING HARNESS	1		\$93.46	✓
70	FRONT HEADLAMP WIRING HARNESS	1		\$88.79	✓
71	FRONT AMBIENT AIR SENSOR	1		\$1.83	✓
72	FRONT AIR VENT ASSY	1		CM \$186.92	✓
73	FRONT RADAR SENSOR	1		\$345.79	✓
74	FRONT RADAR SENSOR BRACKET	1		\$4.67	✓
75	FRONT RADAR SENSOR SUPPORT BRACKET	1		\$7.48	✓
76	FRONT AIRCON CONDENSER	1		Bj/Pu \$420.56	✓

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10/02/2022
Vehicle No: SND1222H
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7EC6MC384844-2021
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SJM801T
Date of Accident: 05/02/2022
Estimator: TING AN
Surveyor:

77	FRONT AIRCON CONDENSER COOLING FAN & SHROULD	1	CM	\$373.83	✓
78	FRONT AIRCON CONDENSER PRESSURE PIPE	1		\$252.34	?
79	FRONT AIRCON CONDENSER DISCHARGE PIPE	1		\$224.30	?
80	FRONT FENDER LH	1		\$448.60	?
81	FRONT FENDER RH	1	Re	\$448.60	✓
82	FRONT FENDER INNER SHIELD LH	1		\$116.82	?
83	FRONT FENDER INNER SHIELD RH	1		\$116.82	?
84	FRONT RIM RH	1	Re	\$1,009.35	✓
85	FRONT SUBFRAME ASSY	1		\$1,177.57	?
86	FRONT AABSORBER RH	1		\$429.91	?
87	FRONT UPPER ARM RH	1		\$116.82	?
88	FRONT LOWER ARM RH	1		\$233.64	?
89	FRONT KNUCKLE ARM RH	1		\$420.56	?
90	FRONT WHEEL BEARING HUB RH	1		\$149.53	?
91	FRONT DOOR LH	1		REPAIR	
92	FRONT DOOR RH	1		REPAIR	
				SUB TOTAL	\$23,813.02
				LESS 10%	-\$2,381.30
				PARTS TOTAL	\$21,431.72

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	REAR BOOTLID INNER TRIM CLIPS	1		Re \$50.00	—
2	REAR BUMPER CLIPS	1		Re \$60.00	—
3	REAR END PANEL JOINT SEALANT	1		\$80.00	?
4	REAR FENDER QUARTER GLASS SEALANT RH	1		Re \$60.00	405N
5	REAR FENDER INNER SHIELD CLIPS RH	1		Re \$40.00	X
6	FRONT WINDSCREEN GLASS SEALANT	1		Re \$80.00	405N
7	FRONT BUMPER CLIPS	1		Re \$60.00	—
8	FRONT NUMBER PLATE & HOLDER	1		Re \$50.00	455N
9	FRONT TYRE RH	1		\$500.00	?
10	FRONT FENDER INNER SHIELD CLIPS LH	1		Re \$40.00	—
11	FRONT FENDER INNER SHIELD CLIPS RH	1		Re \$40.00	—
12	PPF WRAP FOR AFFECTED AREAS	1	(Bill)	\$3,000.00	?
				S/N TOTAL	\$4,060.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10/02/2022
Vehicle No: SND1222H
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7EC6MC384844-2021
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SJM801T
Date of Accident: 05/02/2022
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

2000
\$3,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER, REAR FENDER RH, REAR END PANEL, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT DOOR LH, FRONT DOOR RH & ETC.

2200
\$3,000.00

LABOUR CHARGES TO REMOVE & REPLACE FRONT & REAR PARKING SENSOR.

\$200.00 1200

LABOUR CHARGES TO REMOVE & REFIX FRONT BUMPER WIRING HARNESS & ETC. TO EFFECT REPLACE OF FRONT BUMPER.

\$150.00 7

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & UNHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

\$300.00 1200

LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS LH & ETC.

\$150.00 600

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT KNUCKLE ARM RH, FRONT UPPER & LOWER ARM RH, FRONT WHEEL BEARING RH & ETC.

\$350.00 7

LABOUR CHARGES TO REMOVE & REPLACE FRONT SAFETY BELT LH & RH, FRONT PASSENGER AIRBAG, FRONT STEERING WHEEL AIRBAG & ETC.

\$500.00 2800

LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT DASHBOARD & ETC.

\$400.00 2500

TO DIAGNOSIS & RESET AIRBAG CONTROL UNIT.

\$300.00 2000

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

\$200.00 1200

TO WHEEL ALIGNMENT & BALANCING.

\$100.00 200

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$120.00 400

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10/02/2022
Vehicle No: SND1222H
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7EC6MC384844-2021
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SJM801T
Date of Accident: 05/02/2022
Estimator: TING AN
Surveyor:

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$250.00

90/

TO REALIGN CHASSIS & ETC.

\$300.00

7

LABOUR TOTAL \$9,320.00

TING AN

TOTAL \$34,811.72

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

