

Plate Number SMZ1630J	Case Number MFL2022D0000715	Brand Porsche	Model Details Cayenne	Body Type SUV	Insurance company -	Export CSV
Technician -	SA LKK_assignments	Parts Manager -				

## Parts

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
01	REAR BUMPER ASSY <input type="button" value="Customized"/>			\$0.00	\$1950.00	0 %	1	\$1950.00
02	BUMPER LEFT SIDE TRIM COVER CENTER SIDE <input type="button" value="Customized"/>			\$0.00	\$1200.00	0 %	1	\$1200.00
03	REAR TAILGATE <input type="button" value="Customized"/>			\$0.00	\$4780.00	0 %	1	\$4780.00
04	REAR REINFORCEMENT <input type="button" value="Customized"/>			\$0.00	\$1137.50	0 %	1	\$1137.50
05	REINFORCEMENT TOP TRIM BRACKET <input type="button" value="Customized"/>			\$0.00	\$980.00	0 %	1	\$980.00
06	LOWER LIP <input type="button" value="Customized"/>			\$0.00	\$1550.00	0 %	1	\$1550.00
07	LOWER LIP COVER <input type="button" value="Customized"/>			\$0.00	\$960.00	0 %	1	\$960.00
08	PORSCHE LOGO <input type="button" value="Customized"/>			\$0.00	\$380.00	0 %	1	\$380.00
09	CAYENNE LOGO <input type="button" value="Customized"/>			\$0.00	\$220.00	0 %	1	\$220.00

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
10	REAR TAILGATE WEATHER STRIP <input type="button" value="Customized"/>			\$0.00	\$495.80	0 %	1	\$495.80
11	REAR TAILGATE LOCK MECHANISM <input type="button" value="Customized"/>			\$0.00	\$635.00	0 %	1	\$635.00
12	REAR TAILGATE LOCK COVER <input type="button" value="Customized"/>			\$0.00	\$125.00	0 %	1	\$125.00
13	REAR SENSOR LEFT SIDE 1 <input type="button" value="Customized"/>			\$0.00	\$350.00	0 %	1	\$350.00
14	BUMPER CABEL HOLDER - SINGLE USE <input type="button" value="Customized"/>			\$0.00	\$180.00	0 %	1	\$180.00
15	WINDSCREEN NEED REMOVE, WINDSCREEN SEAL IN SINGLE USE AND COMES WITH WHOLE WINDSCREEN <input type="button" value="Customized"/>			\$0.00	\$1200.00	0 %	1	\$1200.00
							Total :	\$16143.30

## Materials

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
01	REAR BUMPER CLIPS <input type="button" value="Customized"/>			\$0.00	\$30.00	0 %	1.0	\$30.00
02	REAR BUMPER SIDE COVER CLIPS <input type="button" value="Customized"/>			\$0.00	\$30.00	0 %	1.0	\$30.00

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
03	REAR NO PLATE WITH C ASING <input type="text" value="Customized"/>			\$0.00	\$45.00	0 %	1.0	\$45.00
								Total :\$105.00

## Labors

### Replace / RnR

#	Description	Labor Code	Type	Labor Hour	Unit Price	Mark up/Disc	Sum
01	LABOUR FOR PANEL BEATI NG, CUT, WE LD, STRAIGH TEN FRONT A FFECTED AR EA AND REPL ACE FRONT DAMAGED PA RTS, INCLUDI NG REAR EN D PANEL <input type="text" value="Customized"/>		RnR	0.00	\$600.00	0 %	\$600.00
02	TO APPLY AN TI RUST PRO OFING TO FR ONT AFFECT ED AREA <input type="text" value="Customized"/>		RnR	0.00	\$40.00	0 %	\$40.00
03	TO REMOVE AND INSTALL TAILGATE LO CK MECHANI SM ASSY <input type="text" value="Customized"/>		RnR	0.00	\$80.00	0 %	\$80.00
04	TO CHECK R EAR LIGHTIN G AND WIRIN G <input type="text" value="Customized"/>		RnR	0.00	\$40.00	0 %	\$40.00

#	Description	Labor Code	Type	Labor Hour	Unit Price	Mark up/Disc	Sum
05	ACCIDENT AT REAR, REMOVE ACCIDENT MODULE CHECK AND CODING <input type="text" value="Customized"/>		RnR	0.00	\$150.00	0 %	\$150.00
06	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR <input type="text" value="Customized"/>		RnR	0.00	\$40.00	0 %	\$40.00
07	TO REMOVE AND INSTALL REAR REVERSING CAMERA <input type="text" value="Customized"/>		RnR	0.00	\$40.00	0 %	\$40.00
08	REPLACE WINDSCREEN TO FACILITATE THE REPAIR <input type="text" value="Customized"/>		RnR	0.00	\$120.00	0 %	\$120.00
09	RE-PROGRAMMING AND CODING <input type="text" value="Customized"/>		RnR	0.00	\$150.00	0 %	\$150.00
Total :\$1260.00							

Paint

#	Description	Labor Code	degree	Labor Hour	Unit Price	Mark up/Disc	Sum
01	TO PUTTY AND SPRAY PAINTING DAMAGED AREA <input type="text" value="Customized"/>		Full spray	0.00	\$600.00	0 %	\$600.00
Total :\$600.00							

**Remarks** 1 remarks

**2022-09-29 23:27 Assessor Supervisor-Insurlogic 4 42797773348**

Final review based on the information provided by LKK Auto Consultants Pte Ltd: Concluded lump sum repair cost



---