

ASS. REC BY: Taufik

REF: CS/GKB2200.1319/Tufs.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To inspect/ehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____
(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$415K.

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3-Val.: Yes or No

CA / REV / REP. / 24 HRS WP'

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMZ1630J Yr Regn: 2021, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____

Make: Porsche Cayenne V6 c.c 2995

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 21335 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WP1227947 + MPA 42042

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 255/30R22
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front 6 mm Rear 6 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 15/2/22

Survey held at Xin Yan.

Des. of Damages: Frit / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time	Action / Instruction

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.L: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

- Add Fee:
- : Site Insp (\$ _____)
 - : Interview (\$ _____)
 - : Tech. Invs (\$ _____)
 - : Weekend (\$ _____)

Survey Fee:

Transportation:	_____ S + RS. _____ SI
Photos	_____
Others	_____
TOTAL	_____



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMZ1630J Porsche Cayenne 2022 Model

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	1950 \$ 3,257.15 de ✓
2	2	Bumer both side bracket (singel use)	\$ 1,000.00 X un
3	1	Bumper left side trim cover CTR Shb	1200 \$ 2,550.00 de ✓
4	1	Bumper both side trim cover CTR Shb	\$ 2,550.00 X R
5	2	Bumper refector	\$ 300.00 X un
6	2	Bumper both side bracket	\$ 260.00 X un
7	1	Rear tailgate	4780 \$ 5,780.30 bt ✓
8	1	Rear reinforcement	1137.50 \$ 3,190.00 bt ✓
9	2	Tailgate absorber	\$ 1,800.00 X
10	1	Auto door module	\$ 650.00 X
11	1	Auto door sensor-kick open module	\$ 850.00 X
12	1	Accident module which inside tailgate	\$ 850.00 X
13	1	Power window cushion cover-inside tailgate	\$ 200.00 X
14	1	Tailgate middle trim 1 piece comes with reverse camera	\$ 2,500.00 X
15	1	Rear reinforcement	\$ 3,190.00 X repeated.
16	1	Reinforcement top trim bracket	\$ 980.00 de ✓
17	1	Tow cover	\$ 150.00 X un
18	1	Lower lip	1550 \$ 2,565.15 de ✓
19	1	Lower lip cover	960 \$ 1,690.00 de ✓
20	1	Lower lip middle trim	\$ 600.00 X un
21	1	Porsche logo	\$ 380.00 ne ✓
22	1	Cayenne logo	\$ 220.00 ne ✓
23	1	Rear tailgate weatherstrip	\$ 495.80 twi ✓
24	1	Rear tailgate lock mechanism	\$ 635.00 bt ✓
25	1	Rear tailgate lock cover	\$ 125.00 dis ✓
27	2	Rear tailgate no plate lamp	\$ 500.00 X un
28	1	Rear joint tailgate lamp	\$ 3,820.80 X un
29	1	Tailgate top chrome	\$ 295.00 X un
30	1	Rear fender light cover	\$ 195.85 X un
31	1	Rear fender light cover	\$ 195.85 X un
32	1	Accident module	\$ 1,289.95 X un
33	1	Rear sensor ^{left} right side 1	350 \$ 450.00 un ✓
34	1	Rear sensor right side 2	\$ 450.00 X un
35	1	Exhaust cover left	\$ 500.00 X un
36	1	Exhuast cover right	\$ 500.00 X un.
37	1	Bumper cabel holder -single use	\$ 180.00 dis ✓
		Windscreen need remove, windscreen seal is single use	
38	1	and comes with whole windscreen	\$ 1,500.00 ne ✓
39	1	Spoiler 1	\$ 500.00 X un.
		Parts sub-total	\$ 47,145.85

16443.30



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMZ1630J Porsche Cayenne 2022 Model

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips	\$ 120.00 30 net ✓
2	12	Rear bumper side cover clips	\$ 80.00 30 net ✓
3	6	Rear end lower panel top garnish clips	\$ 100.00 X
4	8	Rear tailgate inner trim board clips	\$ 120.00 X
5	6	Rear tailgate outer garnish clips	\$ 80.00 X
6	20	2 pieces spoiler's clips	\$ 100.00 X
7	12	Fender trim clips	\$ 60.00 X
9	8	Lower lip clips	\$ 80.00 X
10	1	Rear end panel sealant	\$ 120.00 X
11	1	Rear no plate with casing	\$ 100.00 H5 bt ✓
Total specail nett item			<u>\$ 960.00</u>

105



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMZ1630J Porsche Cayenne 2022 Model

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts, including rear end panel	\$ 3,000.00 600
2	To putty and spray painting damaged area	\$ 3,000.00 600
3	To apply anti rust proofing to front affected area.	\$ 250.00 40
4	To remove and install tailgate lock mechanism assy.	\$ 150.00 80
5	To check rear lighting and wiring.	\$ 120.00 40
6	Accident at rear, remove accident module check and coding	\$ 500.00 150
7	To remove and install rear bumper reverse sensor.	\$ 150.00 40
8	To remove and install rear reversing camera	\$ 150.00 40
9	To conduct chassis alignment.	\$ 350.00 XUN
10	To conduct wheel alignment.	\$ 120.00 XUN
11	Ceremic coating for rear	\$ 800.00 XUN
12	Water test after repair	\$ 120.00 XUN
13	Remove both fender internal trim to facilitate this repair	\$ 250.00 XUN
14	Replace windscreen to facilitate the repair	\$ 300.00 120
15	Replace the logo replace on the rear joint light	\$ 300.00 XUN
16	Re-programming and coding	\$ 300.00 150
Total labour :		\$ 9,860.00 1860

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495749 16443.50
 WP 15/2/22 105
 1860
 1/5 Resurvey after repair 18408.50
 tanpin@lkkauto.com 4/5 \$14700
 05 days 05 days