



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 4918C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT MUDGUARD	NOT NECESSARY	75.00	-
1	FRONT WHEEL SHAFT	NOT NECESSARY	130.00	-
1	FRONT WHEEL BEARING	NOT NECESSARY	80.00	-
1	FRONT DISC ROTOR	NOT NECESSARY	200.00	-
1	STEM STEERING	NECESSARY	165.00	165.00
1	HANDLEBAR	BENT	80.00	80.00
1	CLUTCH LEVER	CUT	40.00	40.00
1	BRAKE LEVER	NOT NECESSARY	40.00	-
2	BALANCER @\$25.00	CUT (1 PC ONLY)	50.00	25.00
2	SIDE MIRROR @\$30.00	BROKEN	60.00	60.00
1	FRONT HEADLAMP COVER	NOT NECESSARY	60.00	-
1	REAR HEADLAMP COVER	NOT NECESSARY	60.00	-
2	FRONT SIGNAL LAMP @\$25.00	NOT NECESSARY	50.00	-
1	HEADLIGHT ASSY	NOT NECESSARY	160.00	-
1	BELLY SHIELD COVERING	NOT NECESSARY	90.00	-
1	FRONT SIDE FAIRING LH	NOT NECESSARY	95.00	-
1	FRONT SIDE FAIRING RH	NOT NECESSARY	95.00	-
1	CENTRE COVERING	NOT NECESSARY	120.00	-
1	FRONT FOOTREST BAR	BENT	75.00	75.00
2	FRONT FOOTREST RUBBER @\$45.00	CUT (1 PC ONLY)	90.00	45.00
1	GEAR PEDAL	BENT	50.00	50.00
1	BRAKE PEDAL	NOT NECESSARY	80.00	-
1	REAR LH FOOT REST	NOT NECESSARY	45.00	-
1	REAR LH FOOT REST BRACKET	NOT NECESSARY	80.00	-
1	EXHAUST PIPE	NOT NECESSARY	400.00	-
1	EXHAUST PIPE COVER	CUT	65.00	65.00
	LESS 10% DISCOUNT		-253.50	-60.50
			2,281.50	544.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT FORK SEAL (SN)	NOT NECESSARY	80.00	-



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FORK OIL (SN)	NOT NECESSARY	300.00	-
1	REAR BOX (SN)	CUT	350.00	300.00
1	REAR BOX BRACKET (SN)	BENT	150.00	100.00
1	LH ROUND BOX (SN)	NOT NECESSARY	120.00	-
1	NO PLATE (FRONT)(SN)	NOT NECESSARY	20.00	-
1	SET BODY STICKER (SN)	NOT NECESSARY	180.00	-
			1,200.00	400.00
	<b>LABOUR</b>			
	TOWING.		100.00	60.00
	TO REALIGN BODY FRAME.	NOT NECESSARY	350.00	-
	TO R&R FRONT SUSPENSION,HANDLE BAR,HEADLAMP,SIDE FAIRING,AND ATTACHMENTS.		400.00	250.00
			850.00	310.00
<b>GRAND TOTAL</b>			<b>4,331.50</b>	<b>1,254.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,000.00</b>

Report Ref No. CS/AGI22001320/Evf3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.