



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

2010/Adnan

DRIVE NETWORK PTE LTD
7 JALAN INSAF THOMSON RISE ESTATE
SINGAPORE 578009

Contact : 84690003, 82657555

TP chin
Veron

TAX INVOICE

Repair Code : CLM17094

Date in : 09/02/2022

Vehicle Num. : SMZ691P

Model : SUZUKI SWIFT 1.2 GLX CVT

Chassis/Eng# : JSAAZCA3S00523072/K12D1098555

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Delord</i>	1	510.40	510.40
REAR BUMPER REVERSE SENSOR HOLDER BRACKET <i>neu</i>	4	28.00	112.00
REAR BUMPER RH REVERSE SENSOR <i>1 piece demand</i>	1	330.00	330.00 200
REAR BUMPER RH REVERSE SENSOR 'O' RING <i>neu</i>	1	10.00	10.00
REAR BUMPER SIDE RETAINER L/R <i>214 neu</i>	2	20.00	40.00 20
REAR RH FENDER INNER SHIELD <i>Delord</i>	1	128.05	128.05
REAR RH TAILLAMP <i>neu</i>	1	512.60	512.60
REAR RH TAILLAMP PANEL <i>neu</i>	1	57.50	57.50
Subtotal before discount			1,700.55
Percentage discount 15%			255.08
Sub-total 1			1,445.47
REAR BUMPER CLIPS - SET <i>neu</i>	1	50.00	50.00 30
REAR RH FENDER INNER SHIELD CLIPS - SET <i>neu</i>	1	50.00	50.00 30
REAR RH TAILLAMP CLIPS - SET <i>neu</i>	1	30.00	30.00
Subtotal before discount			130.00
Percentage discount 0%			0.00
Sub-total 2			130.00
Parts-total			1,575.47

*** This is a computer-generated document which requires no signature.***

Ka Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

DRIVE NETWORK PTE LTD
7 JALAN INSAF THOMSON RISE ESTATE
SINGAPORE 578009

Contact : 84690003, 82657555

TAX INVOICE

Repair Code : CLM17094

Date in : 09/02/2022

Vehicle Num. : SMZ691P

Model : SUZUKI SWIFT 1.2 GLX CVT

Chassis/Eng# : JSAAZCA3S00523072/K12D1098555

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

30. 50.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

120.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

860

400. 700.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

400. 600.00

To apply anti-rust chemical on repaired and replaced panel.

30. 50.00

Labour Total

1,520.00

Parts & Labour Total

3,095.47

Adrian Lj
h/s 042

*** This is a computer-generated document which requires no signature.***

page 2

total: 1753.38
h/s: 1.4K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: