

Our Job Ref No : 305503407  
Date : 12/02/22

**COMFORTDELGRO  
ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8158

**FINALIZATION FORM**

To : LKK  
Attn : THEVAN  
Vehicle Reg No. : SHA4543Z

Fax :


02/02/22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SBY8085Y
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges
- Total for Part-By-Part Repair Cost**
- (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less:  
**Final Lumpsum Repair cost** \$3,250.00

3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as **Correct and Confirmed** if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : CHIANG  
Tel : 62148314  
Fax : 65468156

Signature :   
Name :  
Date :

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

# REPAIR ESTIMATE\*

VEHICLE NO SHA4543Z

DATE 02/02/22 01:50 AM

MAKE REG.20.10.2019

MODEL : HYUNDAI IONIQ G3

CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET RH			\$35.00
1	FRONT DOOR PANEL RH			\$1,797.20
1	FRONT DOOR MOULDING RH			\$110.10
1	RH SIDE ROCKER GARNISH			\$290.00
1	FRONT FENDER RH			\$588.80
1	FRONT FENDER EMBLEM			\$26.60
1	FRONT WHEEL COVER RH			\$346.40
	<b>SUB TOTAL</b>			<b>\$3,194.10</b>
	<b>20.00%</b>			<b>\$638.82</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$2,555.28</b>
1	FRONT DOOR COMFORT LOGO STICKER			\$75.00
1	FRONT DOOR ADVERTISEMENT			\$100.00
1	FRONT FENDER ADVERTISEMENT			\$100.00
				<b>\$275.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$750.00
	Spray Paint			\$700.00
	Transfer Door Part			\$90.00
	Reset Wheel alignment			\$60.00
	Check lighting			\$90.00
	<b>TOTAL LABOUR</b>			<b>\$1,690.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$4,520.28</b>
<p>Thuan@Uthauto.com 82235769 3/2/22 1630 LIS with a the repair photo wp 3 days</p>				<p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p>
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				