

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK -

DATE: 3-Feb-22INSURANCE: NTUC (LIS)MODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHC 736A - CityCab

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Frt Fender LH	1		\$588.80
	Frt Fender Shield LH	1		\$164.70
	Frt Fender Blue-Drive LH	1		\$26.60
	Frt Wheel Cap LH	1		\$346.40
	Headlamp LH	1		\$1,993.65
	Frt Bumper	1		\$430.90
	Frt Bumper Upper Moulding	1		\$368.50
	Frt Bumper Side Bracket LH	1		\$35.00
	Frt Bumper Clips	10	\$2.20	\$22.00
	Daylight LH	1		\$642.50
	Daylight Grille LH	1		\$93.45
	SUB TOTAL			\$4,712.50
	LESS 20%			\$942.50
	DISCOUNTED TOTAL			\$3,770.00
	Labour Charge			
	Panel Beating			\$800.00
	Spray Painting Charge			\$600.00
	Check Lightings			\$60.00
	Tuff Kote			\$60.00
	Wheel Alignment			\$120.00
	TOTAL LABOUR			\$1,640.00
	ESTIMATE TOTAL			\$5,410.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan@Lkhauto.com
82235769

3/2/21 1600

LIS after repair photo
wp 3days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: