COMFORTDELGRO Our Job Ref No : 305503408 ENGINEERING * Date 12/02/22 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 **FINALIZATION FORM** LKK Fax: Attn : **THEVAN** Vehicle Reg No. : SHA3036C 30.01.2022 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-Z The repair job shall bill to: NTUC SLG6093M 2. The finalized amount shall be: Spare Parts after List discount (a) (b) Labour Charges Total for Part-By-Part Repair Cost (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost \$3,200.00 3. 3 Estimated normal period for repairs: working days. 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days We confirm the estimates and 5. Thank you for your assistance. finalized amount Signature: Signature: : CHIANG Name Name Tel : 62148314 Date : 65468156 Fax For Official Use Only Document Confirm By Remarks Attached Item Amount (Signature) Yes or No YES 1. Rental Rate P/Day N Loss of Income Paid Survey Fees \$7.49/\$2.00 4. LTA Search Fee 5. Medical Fees (on behalf of driver, if applicable) Overrun

Remarks:

REPAIR ESTIMATE*

VEHICLE NO

SHA3036C

MAKE/REG

19.12.2019

DATE 30/01/2022 CHIANG/NTUC

: HYUNDAI IONIQ G3				
	T	The state of the s	Amount	
Parts Description/ Labour	Туре		\$588.80	1/101
		1 1	\$26.60	
The state of the s			\$35.00	ne
I				
			,	
1 LH SIDE ROCKER GARNISH	9.		\$1,797.20	DT
1 FRONT DOOR LH			\$1,737.20	XSVC
				1
1 FRONT DOOR OUTER MOULDING LH			,	
1 LH WHEEL CAP FRT		I -		13(1
		l -		
DISCOUNTED TOTAL		-	34,027.70	
SPONT DOOR COMFORT STICKER		l	\$75.00	MIC
- 1 March 1		l F		
1REAR DOOR COMFORT APP	10.00%		\$139.50	
Labour Charge				
				_
			100	2
, ,				60
				30
TOTAL LABOUR			\$1,680.00	
ESTIMATE TOTAL		-	\$5,847.26	
	FRONT DOOR WING MIRRORR LH FRONT DOOR OUTER MOULDING LH LH WHEEL CAP FRT SUB TOTAL LESS 20% DISCOUNTED TOTAL FRONT DOOR COMFORT STICKER REAR DOOR COMFORT APP Labour Charge Panel Beating Spray Painting Charge Remove/refix door parts Check Wiring	1 FRONT FENDER EMBLEM 1 FRONT BUMPER SIDE BRACKET LH 1 FRONT BUMPER 1 LH SIDE ROCKER GARNISH 1 FRONT DOOR LH 1 FRONT DOOR WING MIRRORR LH 1 FRONT DOOR OUTER MOULDING LH 1 LH WHEEL CAP FRT SUB TOTAL LESS 20% DISCOUNTED TOTAL 1 FRONT DOOR COMFORT STICKER 1 REAR DOOR COMFORT APP 10.00% Labour Charge Panel Beating Spray Painting Charge Remove/refix door parts Check Wiring	1 FRONT FENDER EMBLEM 1 FRONT BUMPER SIDE BRACKET LH 1 FRONT BUMPER 1 LH SIDE ROCKER GARNISH 1 FRONT DOOR LH 1 FRONT DOOR WING MIRRORR LH 1 FRONT DOOR OUTER MOULDING LH 1 LH WHEEL CAP FRT SUB TOTAL LESS 20% DISCOUNTED TOTAL 1 FRONT DOOR COMFORT STICKER 1 REAR DOOR COMFORT APP 10.00% Labour Charge Panel Beating Spray Painting Charge Remove/refix door parts Check Wiring	\$26.60 \$26.60 \$35.00 \$430.90 \$430.90 \$290.00 \$1,797.20 \$1,797.20 \$1,797.20 \$1,797.20 \$1,797.20 \$1,391.70 \$1,006.94 \$25,034.70 \$1,006.94 \$4,027.76 \$1,006.94 \$25,000 \$1,00% \$1,00% \$1,00% \$1,00% \$1,00% \$1,00% \$1,000

Theranolyhauto. (on 82235769 3/2/22 1615 LIS after repair photo wp 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: