

COMFORTDELGRO ENGINEERING

REPAIR ESTIMATE*

DATE 02/02/22 12:00 AM

CHIANG/NTUC

VEHICLE NO SHC8563D

MAKE 10/12/15

MODEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER		DT	\$1,052.20
10	BUMPER CLIP		ncc	\$2.20
1	FRONT BUMPER GRILLE LH		src	\$187.20
1	HEADLAMP LH		rid	\$1,338.00
1	HEAD LAMP SUPPORT PANEL		src X 7.	\$907.40
1	FRONT FENDER LH		DT	\$663.00
1	FRONT FENDER SHIELD LH		"	\$174.90
1	FRONT WHEEL COVER LH		scr	\$217.20
1	FRONT BUMPER BRACKET /LH		nrc	\$24.60
SUB TOTAL				\$4,566.70
20.00%				\$9,133.34
DISCOUNTED TOTAL				\$3,653.36
Labour Charge				
Panel Beating				
Spray Painting				
Reset Front Wheel Alignment				
Check lighting				
TOTAL LABOUR				\$1,560.00
ESTIMATE TOTAL				\$5,213.36
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

tharon@lkhauto.com

82235769

3/2/22 16:00 1700

L/S after repair photo

3 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: