

TP A16
Xiao Tony

GF7W0601476

ESTIMATE OF REPAIR

Veh# : SKW979A

Model:

MIT OUT LANDER

21/8/2019

Accident Date : 10/2/2022

Location : AYE (TUAS) BEFORE NORMANTON PARK EXIT

3P:

SFM338L (AIG)

S/No	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Dehd</i>	1,323.20	980	
2	10 pcs	Rear bumper clips <i>neu</i>		40.00	✓
3	2pcs	Rear bumper screw middle <i>neu</i>		10.00	x.
4	1 pc	Rear bumper lower diffuser <i>Dehd</i>	480.10	380	
5	2 pcs	Rear bumper o/s & n/s retainer <i>neu</i>	168.00	-	
6	2 pcs	Rear bumper o/s & n/s retainers middle <i>neu</i>	188.40	x.	
7	2pcs	Rear bumper o/s & n/s reflector <i>Discard</i>	260.80	2 130.40	
8	2pcs	Rear o/s & n/s stay <i>neu</i>	342.40	x.	
9	2pcs	Rear o/s & n/s wheel arch (bumper) <i>neu</i>	420.30	+	
10	1 pc	Rear tail gate <i>Dehd</i>	1,580.60	989.	
11	1 pc	Rear tail gate o/s & n/s reflector <i>neu</i>	1,150.60	x.	
12	1 pc	Rear tail gate weatherstrip <i>cut</i>	255.30	✓	
13	1 pc	Rear tail gate outlander emblem <i>neu</i>	130.70	75	
14	1 pc	Rear tail gate MVE emblem <i>neu</i>	86.60	✓	
15	1 pc	Rear tail gate C&C emblem <i>neu</i>	78.20	✓	
16	1 pc	Rear tail gate emblem <i>neu</i>	65.80	✓	
17	1 pc	Rear tail gate inner trim (lower) <i>cut</i>	342.40	✓	
18	16 pcs	Rear tail gate inner trim clips <i>neu</i>		80.00	30
19	1 pc	Rear tail gate lock (Upper) <i>Discard</i>	577.10	285	
20	1 pc	Rear tail gate handle <i>neu</i>	242.60	x.	
21	1 pc	Rear tail gate buzzer <i>cut</i>	140.40	✓	
22	2pcs	Rear o/s & n/s tail lamp <i>neu</i>	1,595.00	x.	
23	1 pc	Rear keyless antenna <i>neu</i>	135.00	x.	
24	1 pc	Rear end panel <i>Reps</i>	845.70	x.	
25	1 pc	Rear end panel inner trim <i>Dehd</i>	220.60	✓	
26	6 pcs	Rear end panel inner trim clips <i>neu</i>		30.00	10
27	12pcs	Rear o/s & n/s fender inner trim clips <i>neu</i>		60.00	+
28	2pcs	Rear o/s & n/s fender inner trim <i>neu</i>	1,300.60	+	
29	1 pc	Rear reverse camera <i>Discard</i>		600.00	300.
30	2pcs	Rear reverse sensor <i>Discard</i>		280.00	200
31	1 pc	Rear reg. no. plate <i>green</i>		45.00	+
32	1 pc	Rear reg. no. plate bracket <i>neu</i>		29.00	x.
33	1 pc	Front bumper <i>Dehd</i>	1,234.70	x	
34	10 pcs	Front bumper clips <i>neu</i>		40.00	+
35	2pcs	Front bumper o/s & n/s retainer <i>neu</i>	166.40	+	
36	1 pc	Front bumper lower diffuser <i>Dehd</i>	665.70	+	
37	1 pc	Front bonnet <i>Dehd</i>	1,305.60	+	
38	1 pc	Front bonnet outlander wording <i>neu</i>	90.50	+	
39	1 pc	Front grille (upper) <i>cut</i>	684.10	+	
40	1 pc	Front grille (upper) base <i>cut</i>	334.30	+	
41	1 pc	Front grill lower <i>cut</i>	455.40	+	

42	2pcs	Front grill lower o/s & n/s chrome garnish	HA canled	265.20	132.60	X
43	1 pc	Front reinforcement	Deled	682.30		
44	1 pc	Front reinforcement lower guard	Best	224.50		
45	2pcs	Front n/s & o/s stay	new	162.20	X	
46	2pcs	Front n/s & o/s head lamp	HA canled	2132.10		X
47	2pcs	Front o/s & n/s wheel arch (fender)	new	438.20		
48	2pcs	Front o/s & n/s wheel arch (bumper)	new	275.60		
49	1 pc	Front undercover	Deled	320.30		
50	1 pc	Front support panel top garnish	Deled	165.20		
51	1 pc	Front support panel	Regis	1,230.30		
52	1 pc	Front n/s/ fog lamp	new	449.20		
53	1 pc	Front n/s/ fog lamp garnish	new	108.20		
54	1 pc	Front n/s radiator side garnish (black)	Deled	150.20		
55	1 pc	Radiator	new			
56	1 pc	coolent	Not in		80.00	
57	1 pc	Condenser	new			
58	1 pc	Rear reg. no. plate	Best		45.00	
59	1 pc	Front reg. no. plate bracket	Deled		29.00	
		Sub Total:		25,602.70	1,368.00	0.00
		41.66 TO S.N. 825		10%	0%	10%
		3750.03	After Less %:	23,042.43	1,368.00	0.00
		Labour				
1		To dismantle damaged parts, straighten & welding.		500	2,000.00	1400
2		To spray painting.		600	1,600.00	1400
3		To remove & refit rear windscreen.		120	160.00	120
4		To remove & replace rear reverse sensor		50	80.00	50
5		To remove & replace rear reverse camera.		50	80.00	50
6		To remove & replace rear tail gate. fittings		80	100.00	80
7		To remove and replace condenser & radiator			140.00	X
8		To remove and refit rear upholstery to facilitate repair		60	150.00	60
9		To check for fault code and resetting			250.00	X
10		To check wiring.		30	80.00	60
11		To re seal anti rust.		40	100.00	60
		Sub Total:			4,740.00	
		Total:			29,150.43	
		after less 20%			23,320.34	

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin L
1/8 14/02/22

blal 5905.03

1/8: 47K
O HADP

1530