

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD252Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Feb 2022
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002698
Chassis No.:	VF1ABL15AUC282187
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	03 Nov 2015
First Registration Date:	03 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Nov 2023
PARF Rebate Amount:	\$12,998.00
Intended COE Rebate Details	
COE Expiry Date:	02 Nov 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,267.00
COE Rebate Amount:	\$9,766.00
Total Rebate Amount:	\$22,764.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Feb 2022

OK

Trans-cA1:D40ab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD252Z

AAD2202-048

NOT Authorized

U/Sy @ 7300/hr Max

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

11 FEB 2022

SHD252Z

VF1ABL15AUC282187

200303878K

RENAULT

LATITUDE

10/02/2022

AIG/SJL9788G

03/11/2015

PART	LIST		
1 BUMPER COVER FRT	\$ B1	747.20	✓
1 BUMPER ABSORBER FRT	\$ M1	394.68	✓
1 BUMPER RETAINER FRT LH	\$ D11	101.40	✓
1 BUMPER SUPPORT FRT	\$ S	10.70	X
1 BUMPER RETAINER FRT RH	\$ D11	101.40	✓
1 BUMPER SUPPORT FRT	\$ S	10.70	X
1 BUMPER UNDERTRAY FRT	\$ CM	292.50	✓
1 BUMPER SPOILER FRT	\$ D11	344.70	✓
1 BUMPER GRILLE LOWER FRT	\$ D11	147.00	✓
1 BUMPER BEAM FRT	\$ B1	663.70	✓
1 BONNET	\$ B1	1,312.70	✓
1 BONNET INSULATOR	\$ S	294.30	X
1 BONNET HINGE LH	\$ D11	237.40	✓
1 BONNET HINGE RH	\$ R	237.40	X
1 BONNET LOCK	\$ B1	152.80	✓
1 RADIATOR GRILLE	\$ CM	969.90	✓
1 RADIATOR GRILLE BADGE 'RENAULT'	\$ M	225.36	✓
1 RADIATOR GRILLE FRAME	\$ CM	686.00	✓
1 FRAME FULL SUPPORT PANEL	\$ CM	592.70	✓
1 FENDER PANEL FRT LH	\$ R	437.10	X
1 FENDER PANEL FRT RH	\$ R	437.10	X
1 A/C CONDENSER	\$ B1P	1,537.80	✓
1 HEADLAMP LH	\$ M1	743.60	✓
1 HEADLAMP RH	\$ M1	743.60	✓
	\$	11,421.74	
10%	\$	1,142.17	
	\$	10,279.57	

Trans-cA1:D40ab Auto Services Pte Ltd

AAD2202-048

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD252Z

Special Nett

1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	λ
1 BUMPER CLIP FRT	\$	na	85.00	66na
1 BUMPER RETAINER CLIP FRT	\$	na	70.00	X
1 BUMPER GRILLE LOWER CLIP	\$	na	70.00	λ
1 LICENSE PLATE WITH HOLDER FRT	\$	na	120.00	45na
1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	X
1SET RADIATOR GRILLE SCREW	\$	na	16.00	✓
1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00	X
TOTAL	\$		533.50	
TOTAL PARTS	\$		10,813.07	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$		3,000.00	88ol
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	6ool
To Rust-Proofing Of The Affected Areas.	\$		170.00	3ol
To reinstall rear bumper parking sensor.	\$	na	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00	X
To repair and realign rear exhaust pipe.	\$	na	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00	X

Trans-cA1:D40ab Auto Services Pte Ltd

AAD2202-048

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD252Z

To transfer of rear end panel fittings, attachment and perform water seepage test. \$ *nn* 170.00 X

To transfer of rear windscreen fittings and conduct water seepage test. \$ *nn* 170.00 X

To check steering geometry and computer wheel alignment \$ *nn* 220.00 X

To Check Electrical Lighting Concerned. \$ 170.00 *20%*

TOTAL \$ 10,580.00

Over All Total \$ 31,672.63

(LUMP SUM)

Repair Days

20 DAYS

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: