



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2303449

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 31/05/2023
Reference CC6/CTI22001342/Kya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLW 8032S
Insured Veh. YQ 5156R
Claim No. SNM22D201172/C02
Policy No. DMCVSNA00155312100
Accident Date 21/01/2022
Inspection Date 10/02/2022

Description	Total
Survey Inspection	280.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	280.00
GST (8%)	22.40
Grand Total	302.40

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22001342/Kya3q2 Date: 31/05/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 5156R	Veh. Inspected	SLW 8032S	
Policy No.	DMCVSNA00155312100	Coverage (\$)	0.00	
Claim No.	SNM22D201172/C02	Excess (\$)	0.00	
Assign From		Assign Date	10/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHD841CMJU631911	Colour	METALLIC RED	
Odometer	21905 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	21/01/2022	Inspection Date	10/02/2022	
Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 8032S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH SIDE MIRROR ASSY	MTG DISTORTED	638.60	638.60
1	REAR RH DOOR	TO REPAIR SEE LABOUR	1,878.30	-
1	REAR RH DOOR OUTER HANDLE	DENTED	68.00	68.00
1	REAR RH FENDER	TO REPAIR SEE LABOUR	1,892.00	-
1	REAR RH FENDER 1/4 GLASS MOULDING	NOT NECESSARY	70.50	-
	LESS 20% DISCOUNT		-909.48	-141.32
			3,637.92	565.28
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR WINDSCREEN & REAR RH FENDER GLASS SEALANT (SN)	NOT NECESSARY	80.00	-
			80.00	-
	<u>LABOUR</u>			
	LABOUR CHARGES FOR REMOVE /REFIT ,CUT/WELD ,PANEL BEAT AND REPLACEMENT OF DAMAGES.INCLUSIVE OF THE REPAIR OF REAR RH DOOR AND REAR RH FENDER .		1,200.00	500.00
	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES.		1,000.00	500.00
	TO CHECK WIRINGS.		40.00	20.00
	TO REMOVE ,REFIT REAR WINDSCREEN GLASS .	NOT NECESSARY	140.00	-
	TO REMOVE ,REFIT REAR RH FENDER 1/4 GLASS.	NOT NECESSARY	100.00	-
	TO REMOVE, REFIT ROOF LINING ,REAR CUSHION AND ATTACHMENTS.		200.00	60.00
	TO SUPPLY AND APPLY ANTI RUST TREATMENT.	NOT NECESSARY	80.00	-
			2,760.00	1,080.00
	GRAND TOTAL		6,477.92	1,645.28
	RECOMMENDED COST OF REPAIRS			1,645.28

Report Ref No. CC6/CTI22001342/Kya3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLW 8032S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLW 8032S

RE-INSPECTION

